NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

Form C-103

SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION FILE U.S.G.S. LAND OFFICE OPERATOR OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name WELL GAS WELL OTHER. Drilling 2. Name of Operator Amerada Petroleum Corporation - 3. Address of Operator P. O. Box 668 - Hobbs, New Mexico 1	DISTRIBUTION	HOBBS OFFICE O.C.C.	Supersedes Old
ABAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT LEST THIS TRANSPORT AND CONTROL OF THE STANDARD OF THE STA	SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
ABAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT LEST THIS TRANSPORT AND CONTROL OF THE STANDARD OF THE STA	FILE	APR 31 11 35 AM '59	
SUNDRY NOTICES AND REPORTS ON WELLS TO HOST HOST STATEMENTS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS THE STATEMENT STATEMENT STATEMENT STATEMENT STATEMENT RECEIVED. THE STATEMENT STATEMENT STATEMENT STATEMENT STATEMENT RECEIVED. THE STATEMENT STATEMENT STATEMENT STATEMENT STATEMENT RECEIVED. THE STATEMENT ST	U.S.G.S.	.	5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS OF ANY WASHINGTON TO BE SEARCH TO THE STAND THE STAND	LAND OFFICE		State XX Fee.
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT UNK THIS PROME OF AND ADDRESSES AND THE SECRET OF A STATE OF A STA	OPERATOR		5. State Oil & Gas Lease No.
The properties of Character of			K-3573
The properties of Character of	SUNDR	Y NOTICES AND REPORTS ON WELLS	
The properties of Character of	(DO NOT USE THIS FORM FOR PRO USE **APPLICAT	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
WELL WILL WILL STATE HAVE DEFINED Amercada Petroleum Corporation - Andersea of Contractor P. O. Box 668 - Hobbs, New Mexico 10. Field and Fool, or Wild-cet Wildcat FILE East Lies, Section 19 Townself 14S Name of North Single Age of North Si	1.		7. Unit Agreement Name
Amerada Petroleum Corporation - 3. Address of Chemeter P. O. Box 668 - Hobbs, New Mexico 1. Certain of Well WIT LETTER B 660 FEET FROM THE NORTH 15. Elevation (Show whether Dr. R.T., GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PELS AND ABANDON PULL OR ALTER CARING OTHER		OTHER. Drilling	
Antires of Operators P. O. Box 668 - Hobbs, New Mexico 1. Location of Well UNIT LETTER B 660 FEST FROM THE NOTTH LINE AND 1980 FEST FROM THE AUTOMOTHE LINE AND 1980 FEST FROM THE LINE AND 1980 TO FREE ST. LINE, SECTION 19 TO FREE ST. LIN	2. Name of Operator		8. Farm or Lease Name Unit
2. Address of Operator P. O. Box 668 - Hobbs, New Mexico 1. Check Hobbs, New Mexico 1. D. Field and Pool, or Wildows 1. D. Field and Pool, or Wildows 1. D. Field and Pool, or Wildows Wildows Fire East 1. D. Field and Pool, or Wildows 1. East 1. East 1. D. Field and Pool, or Wildows Wildows Fire East 1. D. Field and Pool, or Wildows 1. D. Field and Pool, or Wildows Wildows 1. D. Field and Pool, or Wildows Wildows Fire East 1. D. Field and Pool, or Wildows Wildows 1. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUS AND ABANDON CHANGE PLANS CHANGE P	Amerada Petroleum Com	rporation -	
4. Location of Well Unit Littles B . 660 PEET FROM THE North LINE AND 1980 PEET FROM THE North LINE AND 1980 PEET FROM THE North LINE AND 1980 PEET FROM THE Willdest Line, Section 19 TOWNSHIP 148 AD57' GL Les Willdest A074' DF 4074' DF 4057' GL Les Nortice OF INTENTION TO: PERFORM REMEDIAL WORR SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORR COMMENCE OFFILING OFFIL. PULL AND ARANDOM COMMENCE OFFILING OFFIL. PULL OR ALTER RADING COMMENCE OFFILING OFFIL. OTHER COMMENCE OFFILING OFFIL. PLUS AND ARANDOMMENT PLUS AND ARANDOMMENT OFFIL OFF	3. Address of Operator		
4. Location of Well Unit Littles B . 660 PEET FROM THE North LINE AND 1980 PEET FROM THE North LINE AND 1980 PEET FROM THE North LINE AND 1980 PEET FROM THE Willdest Line, Section 19 TOWNSHIP 148 AD57' GL Les Willdest A074' DF 4074' DF 4057' GL Les Nortice OF INTENTION TO: PERFORM REMEDIAL WORR SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORR COMMENCE OFFILING OFFIL. PULL AND ARANDOM COMMENCE OFFILING OFFIL. PULL OR ALTER RADING COMMENCE OFFILING OFFIL. OTHER COMMENCE OFFILING OFFIL. PLUS AND ARANDOMMENT PLUS AND ARANDOMMENT OFFIL OFF	P. O. Box 668 - Hobbs	s. New Mexico	1
15. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM MEMBELIAL WORK THE MORBELLA ABANDON OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose mork) SEE RULE 1103. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 its. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8\$ sait per sack and 200 sacks Incor with 7\$ sait per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69, with 1400\$ PP. 29-1/2 hrs. WOC. Tested casing with 1800\$ for 1/2 hr. Held OK. Started drig. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.	4. Location of Well	· · · · · · · · · · · · · · · · · · ·	10. Field and Pool, or Wildcat
15. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM MEMBELIAL WORK THE MORBELLA ABANDON OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose mork) SEE RULE 1103. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 its. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8\$ sait per sack and 200 sacks Incor with 7\$ sait per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69, with 1400\$ PP. 29-1/2 hrs. WOC. Tested casing with 1800\$ for 1/2 hr. Held OK. Started drig. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.	В	660 North 1980	Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4074' DF 4057' GL Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUS AND ABANDON PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OPAS. PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OPAS. PLUS AND ABANDONMENT	UNIT LETTER,	FEET FROM THE FEET FROM	
15. Elevation (Show whether DF, RT, GR, etc.) 4074' DF 4057' GL Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUS AND ABANDON PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OPAS. PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OPAS. PLUS AND ABANDONMENT	East	19 14S 35E	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMMORAPILY ABANDON PULL OR ALTERIAS OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose nork) SEE RULE 1-103. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8# sait per sack and 200 sacks Incor with 7# sait per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69,with 1400# PP. 29-1/2 hrs. WOC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.	THE LINE, SECTION	N TOWNSHIP RANGE NMPM.	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILY ABANDON PULL AND ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing on top (substructure 19,50') set at 4530' with 900 sacks litre wt. cement with 8\$ sait per sack and 200 sacks Incor with 7\$ sait per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69, with 1400\$ PP. 29-1/2 hrs. WOC. Tested casing with 1800\$ for 1/2 hr. Held OK. Started drig. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILY ABANDON PULL AND ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing on top (substructure 19,50') set at 4530' with 900 sacks litre wt. cement with 8\$ sait per sack and 200 sacks Incor with 7\$ sait per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69, with 1400\$ PP. 29-1/2 hrs. WOC. Tested casing with 1800\$ for 1/2 hr. Held OK. Started drig. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.		4074' DF 4057' GL	T.ea ())))))
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILY ABANDON PULLO AND ABANDON OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1 103. Drilled 12-1/4" hole to 4530'. Ren 732' 9-5/8" OD 40\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36\$ K-55 8 rd. ST&C cas	16.		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING THER TO CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPIS. CASING TEST AND CEMEUT 1/03 Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks line wt. cement with 8# sait per sack and 200 sacks Incor with 7# sait per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69.with 1400# PP. 29-1/2 hrs. WCC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.			
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8# salt per sack and 200 sacks Incor with 7# salt per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69, with 1400# PP. 29-1/2 hrs. WOC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.	NOTICE OF IN	TIENTION TO: SUBSEQUENT	REPORT OF:
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8# salt per sack and 200 sacks Incor with 7# salt per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69, with 1400# PP. 29-1/2 hrs. WOC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.			
OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see Rule 1103. Drilled 12-1/4" hole to 4530'. Ren 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks little wt. cement with 8# sailt per sack and 200 sacks Incor with 7# sailt per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69. with 1400# PP. 29-1/2 hrs. WOC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.	PERFORM REMEDIAL WORK		_
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE ROLE 1103. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8# salt per sack and 200 sacks Incor with 7# salt per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69.with 1400# PP. 29-1/2 hrs. WCC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.	TEMPORARILY ABANDON		PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8# sait per sack and 200 sacks Incor with 7# sait per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69.with 1400# PP. 29-1/2 hrs. WOC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'. 18. Thereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE District Superintendent DAYE April 29, 1969	PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB X	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose north) SEE RULE 1193. Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks litre wt. cement with 8# salt per sack and 200 sacks Incor with 7# salt per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69.with 1400# PP. 29-1/2 hrs. WOC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.		OTHER	
Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8# salt per sack and 200 sacks Incor with 7# salt per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69.with 1400# PP. 29-1/2 hrs. wOC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.	OTHER		
Drilled 12-1/4" hole to 4530'. Ran 732' 9-5/8" OD 40# K-55 8 rd. ST&C casing w/float shoe on bottom and insert float 2 jts. off bottom, and 3778' 9-5/8" OD 36# K-55 8 rd. ST&C casing on top (substructure 19.50') set at 4530' with 900 sacks lite wt. cement with 8# salt per sack and 200 sacks Incor with 7# salt per sack. Total of 1100 sacks. Pumped plug to 4443' at 3:30 p.m. 4-27-69.with 1400# PP. 29-1/2 hrs. wOC. Tested casing with 1800# for 1/2 hr. Held OK. Started drlg. 8-3/4" hole at 11 p.m. 4-28-69. Top of cement outside 9-5/8" csg. at 2875'.	17 Describe Dranged or Completed Or	parations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
SIGNED TITLE District Superintendent DATE April 29, 1969	shoe on bottom and in ST&C casing on top (a with 8# salt per sac Pumped plug to 4443' casing with 1800# for	nsert float 2 jts. off bottom, and 3778' 9-5/8" substructure 19.50') set at 4530' with 900 sacks k and 200 sacks Incor with 7# salt per sack. To at 3:30 p.m. 4-27-69.with 1400# PP. 29-1/2 hrs r 1/2 hr. Held OK. Started drlg. 8-3/4" hole s	OD 36# K-55 8 rd. lite wt. cement tal of 1100 sacks. . WOC. Tested
	Late) a k		