

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-6606	
7. Unit Agreement Name	
-	
8. Farm or Lease Name	
State "6" Com.	
9. Well No.	
3	
10. Field and Pool, or Wildcat	
Baum (Up. Penn)	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator
	Coastal States Gas Producing Company
3. Address of Operator	
	P. O. Box 235, Midland, Texas 79701
4. Location of Well	
UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM THE <u>west</u> LINE, SECTION <u>6</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
	4301' KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well No. 3 was plugged on 7-18-70 as follows:

1. CI bridge plug set @ 9800' w/2 sxs cement on top
2. Cut 5-1/2" @ 6140'
3. 35 sx plug @ 5500'
4. 50 sx plug @ 4150-3990'
5. Cut 8-5/8" @ 1226'
6. 25 sx plug @ 1226'
7. 35 sx plug @ 425-315'
8. 10 sx plug in top
9. Installed DHM

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joe R. Hammond</u>	TITLE <u>Division Production Manager</u>	DATE <u>September 17, 1970</u>
APPROVED BY <u>John W. Remyer</u>	TITLE <u>Geologist</u>	DATE <u>OCT 21 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

SEP 18 1970

OIL CONSERVATION COMM.
HOBBS, N. M.