

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K 6607	
7. Unit Agreement Name	
8. Farm or Lease Name State 1	
9. Well No. 1	
10. Field and Pool, or Wildcat Baum	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS <small>DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator Coastal States Gas Producing Company	
3. Address of Operator P. O. Box 235, Midland, Texas 79701	
4. Location of Well UNIT LETTER H 1874 FEET FROM THE North LINE AND 554 FEET FROM THE East LINE, SECTION 1 TOWNSHIP 14-S RANGE 32-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 9500' & dump bail cement on BP.
2. Cut off 5-1/2" casing @ approximately 6000'.
3. Set 25 sx. plug @ 6000'.
4. Set 25 sx. plug @ 4800'.
5. Set 30 sx. plug @ 4046'.
6. Cut 8-5/8" casing @ 1000'.
7. Set 25 sx. plug @ 1000'.
8. Set 35 sx. plug @ 365'.
9. Install DHM.

Propose to start work upon Commission approval of procedure.

THIS COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED 	TITLE Dist. Prod. Superintendent	DATE 10-24-73
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		