

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K 544

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL CO., INC.	8. Farm or Lease Name TENNECO STATE
3. Address of Operator P. O. Box 1069 - Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER H , 1874 FEET FROM THE North LINE AND 766 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 14-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Cerca Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4160' RKB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in, rigged up, installed BOP. Pulled rods & tubing.
- Ran collar log. Perforated 1 SPF @ 10,415 to 10,422'.
- Ran tubing w/treating pkr. Spot 250 gal MOD 202 acid over perfs.
- Set pkr @ 10,346'. A/3000 gal acid. Swabbed load. Pulled tubing & pkr.
- Ran tubing, rods & pump. Tested.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed By C. R. Tilley TITLE Area Prod. Foreman DATE 10-12-71

APPROVED BY John W. Runyan TITLE Geologist DATE OCT 13 1971
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED.

DEC 12 1971

OIL CONSERVATION COMM.
HOBBS, N. M.

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K 544	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL CO., INC.		8. Farm or Lease Name TENNECO STATE
3. Address of Operator P. O. Box 1069 - Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER H , 1874 FEET FROM THE North LINE AND 766 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 14-S RANGE 34-E NMPM.		10. Field and Pool, or Wildcat Cerca Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.)		12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in, rig up, set BOP. Pull rods, & tubing.
2. Run collar log. Perf 1 SPF @ 10,415' to 10,422'.
3. Run tubing w/treating pkr. Spot 250 gal. MOD 202 acid over perfs. Set pkr @ 10,350'.
4. Acidize w/ 3000 gal. acid. Swab acid water. Pull tubing & pkr.
5. Run tubing, rods & pump. Test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED	Original Signed by Sheldon Ward	TITLE	Area Superintendent
		DATE	8-20-71
APPROVED BY		TITLE	SUPERVISOR DISTRICT I
CONDITIONS OF APPROVAL, IF ANY:		DATE	AUG 23 1971

RECEIVED

AUG 23 1971

OIL CONSERVATION COMM.
HOBLE, N. M.