

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 3716	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A - Re-Entry	
2. Name of Operator Yates Petroleum Corporation	
3. Address of Operator 207 South 4th St., Artesia, NM 88210	
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>12S</u> RANGE <u>33E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4305.4' GR	

7. Unit Agreement Name
8. Farm or Lease Name Midwest-Hightower ADS St.
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

3-20-86. Cut 5-1/2" casing at 4635' and laid down 114 joints (4654').
Spotted cement plugs as follows:

Set 35 sx Class "C" Neat at 8528-8628' -(5-1/2" cut)
Set 35 sx Class "C" Neat at 4585-4685' -(5-1/2" stub)
Set 35 sx Class "C" Neat at 3930-4030' -(8-5/8" shoe)
Set 35 sx Class "C" Neat at 1590-1690'
Set 35 sx Class "C" Neat at 268-368'
Set 15 sx Class "C" Neat Surface-30'

Install regulation abandonment marker.
Plugging completed 3/21/86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Production Supervisor</u>	DATE <u>3-24-86</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JAN 03 1989</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
MAR 26 1986
HOBBS OFFICE

000 000 000