

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 3716	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug and Abandon		7. Unit Agreement Name	
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Midwest-Hightower ADS St.	
3. Address of Operator 207 South 4th St., Artesia, NM 88210		9. Well No. 1	
4. Location of Well UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 12S RANGE 33E NMPM.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 4305.4' GR		12. County Lea	


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission obtained from Mr. Paul Kautz, NMOCD, Hobbs, 3-17-86, by Mr. Ray Stall, YPC, to P&A well as follows:

Set CIBP at 9400' w/200' cement.
Cut 5-1/2" at 8950' and pull. Set plug 50' in and 50' out of stub.
Set 100' plug 7582-7482' across Abo.
Set 100' plug 5371-5271' across Glorieta
Set 100' plug 4030-3930' across San Andres, 8-5/8" casing shoe.
Set 100' plug 1690-1590' inside 8-5/8" casing, across Anhydrite.
Set 100' plug 368-268' inside 8-5/8" casing (11-3/4" casing set 318')
Set 15 sx surface plug.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Production Supervisor	DATE 3-17-86
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		DATE MAR 20 1986
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
OCT 19 1986
S.C.P.
RECEIVED