

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
LG 3716

7. Unit Agreement Name

8. Farm or Lease Name
Midwest Hightower ADS St.

9. Well No.
1

10. Field and Pool, or WHdcat
Wildcat

12. County
Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER Re-Entry

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
207 South 4th St., Artesia, NM 88210

4. Location of Well
UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 12S RANGE 33E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4305.4' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER _____

PLUG AND ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER Perforate, Treat

ALTERING CASING

PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

2-12-86. Drilled out cement to 10444'. WIH and perforated 10422-31' w/9 .50" holes (1 SPF). Acidized perfs 10422-31' w/1500 gals 15% DS-30 + 12 ball sealers. Swabbed dry.

2-17-86. Set CIBP at 10400' w/35' cement on top. WIH and perforated 10288-94' w/12 .40" holes. Acidized perfs 10288-94' w/1500 gals 15% NEFE acid and 15 ball sealers. Swabbed with no shows.

2-20-86. WIH and perforated 10 .50" holes as follows: 9952-56' (1 SPF); 9979-83' (1 SPF). Acidized perfs 9952-83' and 10288-94' together w/2000 gals 15% NEFE acid + 15 ball sealers. Swabbed with no shows.

Propose to set CIBP within 50' above old perfs 10288-94'. Set cement reatiner at approx. 9930' (above last set of perfs 9952-83'). GIH w/tubing and cement squeeze perfs 9952-83'. Perforate Bough D at 9880-89' (1 SPF) 10 holes. Acidize new perfs w/1000 gals 15% acid and ball sealers. Test well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay TITLE Production Supervisor DATE 2-24-86

APPROVED BY Oil & Gas Inspector TITLE _____ DATE FEB 26 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 25 1986
C. C. P.
HOBBS OFFICE