STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTI	MENT							
		ONSERVA	TION DIV	ISION				
DISTRIBUTION		P. O. BO		Form C-103				
SANTA FE		TA FE, NEW		Revised 10-1-78				
FILE			MEXICO 8	/ 501	Sa. Indicate Type			
V.S.O.S.					State XX			
LAND OFFICE						F ••		
OPERATOR	-1				5. State Oil & Gas	Lease No.		
					к-3013			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO PRILL ON TO DECEMENT OF PLUG BACA TO A DIFFERENT REBERVOIR. USE "TAPPLICATION FOR FORMIT -" (FORM C-101) FOR SUCH PROPOSALS.)								
1. OIL XX GAB .	0THE8-				7. Unit Agreement	Name		
2. Name of Operator						8. Farm or Lease Name		
Dwight A. Tipton						New Mexico 86 State		
3, Address of Operator					9. Well No.			
c/o Oil Reports & Gas	Services, Inc.	, Box 755,	Hobbs, NM	88241	1			
4. Location of Well					10. Field and Poo	l, or Wildcat		
F	F 1980 North 1980				Tres Papalotes Penn			
UNIT LETTER	FEET FROM	THE	LINE AND	FLET FROM	mmm	mmmn.		
		149		315				
THE WEST LINE, SECTION 33 TOWNSHIP 14S RANGE 31E NMPM.								
						<i>HHHHHH</i>		
15. Elevation (Show whether DF, RT, GR, etc.)				12. County				
		4125	DF		Lea	VIIIIII		
	k Appropriate Box	To Indicate N	ature of Not	ice, Report or Ot	her Data			
NOTICE OF INTENTION TO: SUBSEQUENT								
				~~		-		
PERFORM REMEDIAL WORK	PLUG	AND ABANDON	REMEDIAL WORK	· []	ALTERI	NG CASING		
TEMPORARILY ABANDON			COMMENCE DRIL	LING OPHS.	PLUG AT	ND ABANDONMENT		
PULL OR ALTER CASING	CASING TEST AN	ASING TEST AND CEMENT JOB						
			OTHER S	Squeeze Casing	Leak			
					-			
ОТИER	<u> </u>	<b>L</b>	_					

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work began 7-28-86. Found casing leak at 7600. Attempt to pump thru leak, rate too small to squeeze. Shot 2 squeeze holes at 7600. Set retreivable bridge plug at 9990 and cement retainer at 7400, squeezed with 400 sacks Hoco lite and 100 sacks class C cement. Maximum pressure 1800#. WOC 36 hours. Drilled out cement retainer and cement to 7600. Test casing with 1000# for 10 minutes, test 0.K. Clean out to bridge plug and pull same. Ran rods & pump. Pump load water. 9-9-86 pump 12 bbls oil, 79 bbls water, 24 hours.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

1

SIGNED Noneral Selles	TITLE	Agent	DATE_	9-10-86
ORIGINAL SIGNED BY JERRY SEXTON	TITLE		DATE _	5571 1 1986
CONDITIONS OF APPROVAL, IF ANYI				

