

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brizos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-23521

5. Indicate Type of Lease

STATE ☒FEE ☐

6. State Oil & Gas Lease No.

K-4807

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒GAS
WELL ☐OTHER ☐

2. Name of Operator

Coastal Oil & Gas Corporation

3. Address of Operator

P. O. Box 235, Midland, Texas 79702

4. Well Location

Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West LineSection 31 Township 13-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4283' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work was performed from 7/5/95 through 7/12/94 as follows:

MIRU plugging unit. POOH with rods and pump. POOH with tbg. RU WL, set CIBP at 9750'. GIH with bailer, set 35' cement plug on top (9715'-9750'). GIH with tbg, circ hole with 232 bbl 9.5 PPG mud. POOH to 6900', spotted 25 sack plug (6700'-6900'). POOH. Welded on to 5-1/2" csg, pulled stretch, calculated free point. Shot casing at 3427', POOH and LD same. GIH with tbg, could not get inside 5-1/2" csg stub. Checked with OCD (Jerry Sexton), got OK to spot cmt plug on top of stub. Spotted 30 sack plug at 3427'. WOC 3 hrs, tag cmt at 3312' (3312'-3427'). Welded on to 8-5/8" csg, pulled stretch. Shot csg at 363', POOH and LD same. GIH with tbg, spot 40 sack plug inside 8-5/8" csg from 1730'-1630'. Spot 80 sack plug at 415'. WOC 3 hrs and tag plug at 290'. Spotted 30 sack plug from 30' to surface. Installed P&A marker. Well P&A'd 7-12-94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bobby L. Smith

TITLE

Sr. Petroleum Engineer

DATE

07/29/94

TYPE OR PRINT NAME

Bobby L. Smith

TELEPHONE NO. 915-682-7925

(This space for State Use)

APPROVED BY

Cary D. Lipp

TITLE

DATE

COMMENTS OF APPROVAL, IF ANY