

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
-----	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
McGrath & Smith, Inc.		Markham
3. Address of Operator		9. Well No.
418 Building of the Southwest, Midland, Texas 79701		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER K, 1980 FEET FROM THE West LINE AND 2150 FEET FROM		Wildcat
THE South LINE, SECTION 23 TOWNSHIP 12-S RANGE 37-E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
GL 3892 KB 3904		Lea

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

OTHER ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 6-27-70. Drld. 17 1/2 hole to 352'. Cmt. 13 3/8-61# csg. at 352' with 325 sx. Circ. 20 bbls. cmt. Plug down 8:45 am, 6-28-70. WOC 18 hrs. Tstd. 13 3/8 to 600 psi - OK. Drld. 11" hole to 4500'. Cmt. 8 5/8-24 & 32# csg. at 4500' with 450 sx. Plug down 7:00 am, 7-4-70. WOC 18 hrs. Tstd 8 5/8 to 1000 psi - OK. Drld. 7 7/8 hole to TD 11600'. Reached TD on 8-10-70. Ran logs. Propose to P & A as follows: Spot cmt. plugs 35 sx. at 11,600, 25 sx. top Penn, 25 sx. top WC, 25 sx. top Abo, 25 sx top Glor, 25 sx. across base of 8 5/8 at 4500', 25 sx. on 8 5/8 stub, 25 sx. across base of 13 3/8 at 352', 10 sx. in top 13 3/8 from 0-20'. Install DHM.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.B. Taylor TITLE Sup't. DATE 8-13-70

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: