

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-2997

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator BTA Oil Producers	8. Farm or Lease Name Chem 707 JV-D
3. Address of Operator 104 South Pecos, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER "F" 1980 FEET FROM THE North LINE AND 1830 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 14-S RANGE 32-E NMPM.	10. Field and Pool, or Wildcat Baum Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4291 GL, 4302 KB	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure:

35 sx @ 9960-TD
25 sx @ 9485-Penn
25 sx @ 8915-Wolfcamp
25 sx @ 7572-Abo
25 sx @ 5402-Glorietta
25 sx @ 3990-(8-5/8" casing shoe)
Cut & pull 8-5/8" csg.
25 sx @ 8-5/8" csg. stub
If salt is exposed - 25 sx @ top & 25 sx @ base
25 sx @ 382 (12-3/4" csg. shoe)
10 sx @ surface
Install dry hole marker per NMOCC regulations.
Verbal approval by Leslie Clements (NMOCC) @ 4:25 P.M. 10-9-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. D. Boyce TITLE Drilling Manager DATE 10-12-70

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 1 1970

OIL CONSERVATION COMM.
HOUSTON, TEX.