

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-3138
7. Lease Name or Unit Agreement Name Baum State
8. Well No. 2
9. Pool name or Wildcat Baum Upper Penn

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4266' GL
--

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator MWJ PRODUCING COMPANY
3. Address of Operator 400 W., Illinois - Suite 1100 Midland, Tx 79701
4. Well Location Unit Letter L/N : 990/1791 Feet From The West Line and 2310/646 Feet From The South Line Section 5 Township 14S Range 33E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: completion <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/14/89: POOH w/tbg. RU Wedge W/L, ran & set Halliburton cmt retainer @ 10260'. Squeezed w/75 sx cmt @ 500 psi.
6/15/89: Spt'd 1000 gals 15% HCL ac. Perf'd "B" zone from 10156-10172' & 10178-10194' 2 SPF. Ran Baker Model R-3 pkr, SSN, CO & 239-jts 2-3/8" tbg. Swbd.
6/16/89: Acd w/2000 gals 20% HCL ac & 100 7/8" ball sealers @ 6.9 BPM @ 2300 psi. Flushed w/40 BW. ISIP - vacuum. Swbd.
6/17-18: SD.
6/19/89: Ran BHA, 339 jts 2-3/8" tbg & pkr. Top of pkr @ 10116', end of tbg @ 10204'. Ran redressed 1" seal assy & 312 jts 1" vent string. Loaded & circ w/230 BW, press to 1000 psi. Ran pump, started well pmpg.
6/20-26: Pmpg all wtr.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Pat Drexler TITLE Pat Drexler-Agent DATE 6/26/89

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

JUN 29 1989

APPROVED BY DATE

CONDITIONS OF APPROVAL, IF ANY: