

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-4671	
7. Unit Agreement Name	
8. Farm or Lease Name	
State 1-21	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Wildcat	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
Meadco Properties, Ltd.
3. Address of Operator
407 West Wall St., Midland, Texas 79701
4. Location of Well
UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 21 TOWNSHIP 14-S RANGE 32-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
4330.5' GR

16.



Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/6/72 Moved unit to location and rigged unit. Broke wellhead down, ran gage ring on sand line. Made up cast iron bridge plug and ran to 9700' on sand line and set plug. Cleaned out cellar & shut well in.
1/7/72 Opened well up and dumped 2 sacks of cement on top of CIBP at 9700'. Rigged up wire line and shot pipe at 8246'. Pulled head joint out, hooked up pump truck and loaded hole with salt water and circulated to pit. Closed well in for night.
1/8/72 Spotted 25 sack cement plug at 8246', pulled up to 5715' and spotted a 25 sack plug. Pulled up to 4005' and spotted a 25 sack cement plug. Pulled 64 jts. 4½" casing out of well.
1/10/72 Pulled rest of 4½" casing. Rigged up wire line and shot 8-5/8" casing at 1367'.
1/11/72 Tried to work pipe free but failed. Rigged up wireline and shot pipe at 1201'. Pulled pipe free and set a 25 sack cement plug at 8-5/8" stub at 1201'. Pulled up to 408' and set a 25 sack cement plug. Pulled casing out of hole. Put a 10 sack plug at surface and put up dry hole marker.
Total of 8,312.60' of 4½" csg. pulled. Total of 1,277.48' 8-5/8" csg. pulled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Bill C. Cotner, Owner	DATE 2/2/72
APPROVED BY 	TITLE OIL & GAS INSPECTOR	DATE SEP 5 1972
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 5 1972

OIL CONSERVATION COMM.
HOUSTON, TEXAS