N OF COPIES RECEIVED	4			Form C-103 Supersedes Old
DISTRIBUTION SANTA FE	NEW MEXIC	O OIL CONSERVATION	COMMISSION	C-102 and C-103 Effective 1-1-65
U.S.G.S.				Sa. Indicate Type of Lease State X Fee S. State Cil & Gas Lease No.
OPERATOR				L 3374 and LG 0029
SUNDI (DO NOT USE THIS FORM FOR PR USE "APPLICA"	RY NOTICES AND RE	PORTS ON WELLS EPEN OR PLUG BACK TO A DIFF C-1011 FOR SUCH PROPOSALS.	ERENT RESERVOIA.	7. Unit Agreement Name
OIL X GAS WELL	07HER-			
MEWBOURNE OIL COMPANY				6, Form or Lease Name State "A"
Address of Operator				9. Well No. 1
P. O. Box 7698, Tyle			•	10. Field and Pool, or Wildcat
N	2130 FEET FROM THE	West LINE AND	660 FEET FRO	Cerca/Upper Penn
	8	SHIP RANGE		
	15. Elevation	(Show whether DF, RT, GR,	etc.)	12. County Lea
	INTENTION TO:	ABANGGN X REMEDIAL W	SUBSEQUE	TREPORT OF:
TEMPORARILY ABANDON			DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE P		T AND CEMENT JOB	ſ
OTHER			· · · · · · · · · · · · · · · · · · ·	
	Operations (Clearly state a	ll pertinent details, and give	e pertinent dates, includi	ng estimated date of starting any propos
i?. Describe Proposed or Completed (work) SEE RULE 1103. Will set Cast Iron Cut off 4-1/2" with 100' of cement in a 100' in and out of 100' in and out of 10' at top with mar (100' p/ug st e) (100' p/ug st e) (Plug at top perf 100' cement in and out of the 8- the stub of 8-5/ shoe of 12-3/4"	and out of stub. -5/8" shoe. '8" - 4350' - 4450 - 371' - 471'. , If mot be. 14 - 5 (7.54)	with 35' cemen	t on top.
work) SEE RULE 1103. Will set Cast Iron Cut off 4-1/2" with 100' of cement in a 100' in and out of 100' in and out of	Plug at top perf a 100' cement in and out of the 8- the stub of 8-5/ shoe of 12-3/4" ther. $b \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$	The communication of the set of the best of my knowle	with 35' cemen D'. <i>lind pifo</i> <i>min.</i>) SSIGN AUST BE PROF TO CALLET dge and belief. <u>tion Clerk</u>	t on top.