	, ~
DISTRIBUTION SANTA FE FILE U.S.G.S. LAND OFFICE OPERATOR	Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State Fee XX 5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
(DO NOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DEEPEN OR PLUG SACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.) 1.	7. Unit Agreement Name
OIL GAS WELL OTHER-	
Tom L. Ingram	8. Farm or Lease Name Markham
POB 1757, Roswell, New Mexico 88201	9. Well No.
4. Location of Well	10. Field and Pool, or Wildcot SW Glad. Devonian
UNIT LETTER L , 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM	
THE West LINE, SECTION 23 TOWNSHIP 125 RANGE 37E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3894 GR	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUEN	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON XX REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any proposed
7/22/73 Verbal approval from Joe Ramey, NMOCC, to plug and abando 100' plug @ 12,386-12,486; 100' plug @ 9500-9600; 100' plug @ 5800-5900; 100' plug @ 4450-4550.' Will cut a 2000' of 8-5/8 casing. Will set 100' plug in and out of 100' plug @ 375-475. 10 sx. plug @ surface. Erect marks	lug @ 7750-7850; and pull approximately f 8-5/8" stub.
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED OPERATOR	DATE <u>8/8/73</u>
CONDITIONS OF APPROVAL, IF ANY:	DATE