

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No. V. 1413

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name	
2. Name of Operator M & W OF LOVINGTON, INC.	8. Farm or Lease Name CITIES SERVICE STATE	
3. Address of Operator P.O. BOX 922 LOVINGTON, NM 88260	9. Well No. #1	
4. Location of Well UNIT LETTER E 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM THE WEST 26 LINE, SECTION 14s RANGE 34E NMPM.	10. Field and Pool, or Wildcat HIGH PLAINS, PENN	
15. Elevation (Show whether DP, RT, GR, etc.) 4084' GL	12. County LEA	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐
OTHER ☐		ALTERING CASING ☐
		PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. SET BRIDGE PLUG @ 9800'.
2. PERF UPPER WOLFCAMP @ 9680' TO 9716' 1 JET SHOT PER FT.
3. ACIDIZE PERFS WITH 3000 GAL 15% HCL ACID, USING BALL SEALERS.
4. SWABB ACID BACK.
5. RETURN WELL TO PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Johnnie W. Wilson</u>	TITLE <u>PRESIDENT</u>	DATE <u>5-15-85</u>
APPROVED BY <u>Eddie W. Seay</u> Oil & Gas Inspector	TITLE _____	DATE <u>MAY 17 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		