

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K 3714

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO PLUG OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator	8. Farm or Lease Name	
M & W of Lovington, Inc.	Cities Service State	
3. Address of Operator	9. Well No.	
P. O. Box 922, Lovington, N.M. 88260	1 1	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM	High Plains, Penn	
THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>14S</u> RANGE <u>34E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
4084' GL	Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
		OTHER <u>Return Well to Production</u> <input checked="" type="checkbox"/>
		ALTERING CASING <input type="checkbox"/>
		PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set pumping unit.
2. Installed electric power to well.
3. Run tubing and rods.
4. Return well to production.
5. Well pumping 100% H²O.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Prod. Clerk. DATE 6/13/84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 18 1984

CONDITIONS OF APPROVAL, IF ANY: