

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-625-23072
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 1-522
7. Lease Name or Unit Agreement Name State APP + Lea YN State
8. Well No. 1
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator SMITH & MARSH INC.
3. Address of Operator Box 803 Kermit TX 79745	4. Well Location Unit Letter C : 66C Feet From The North Line and 1980 Feet From The West Line Section 27 Township 14S Range 32E NMPM County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4319	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER: <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1- C 16P set 8-26-88 @ 8670' @ 35' cement
2- 25' @ 4150-4000'
3- 7' @ 4000' stub of casing 4000' + AG
4- 50' @ 4000' stub of 8 3/8 pulled
5- 100' @ 451-331
6- 10' @ 10' - SURFACE

13 3/8 - 40' - SURFACE
8 3/8 - 40' - TCC - 2000'
4 1/2 - 9982-270 SXS
squeezed casing
@ 4955-4895
TCC @ 4000'

LOCAL Hole @ mud
install dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE VP DATE 4-9-91
TYPE OR PRINT NAME Richard Smith TELEPHONE NO. 915-551-2544

(This space for State Use)

APPROVED BY [Signature] TITLE APPROVED DATE APR 11 1991
CONDITIONS OF APPROVAL, IF ANY: