

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. State Oil & Gas Lease No. LG-3870
2. Name of Operator John L. Cox		7. Unit Agreement Name
3. Address of Operator Box 2217, Midland, TX 79702		8. Farm or Lease Name State 8
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South 1980 LINE AND FEET FROM East 8 LINE, SECTION 8 TOWNSHIP 12S RANGE 33E NMPM.		9. Well No. 1
15. Elevation (Show whether DF, RT, GR, etc.)		10. Field and Pool, or Wildcat N. Bagley (Penn.)
		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JQB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Reason to P&A - Well not commercial producer.

2. Propose to spot CIBP @9600' w/35' cement on top of plug. (Perforation 9641-9956').

3. Propose to spot 100' cement plug @4-1/2" casing stub (Approx. 4100').

4. Propose to spot 100' cement plug @8-5/8" casing shoe @3750'.

5. Propose to spot 100' cement plug @12-3/4" casing shoe @378'.

6. Propose to spot 10 sx cement plug @surface w/marker.

7. Hole will be filled with mud laden fluid.

8. Tentative date of plugging operations: Upon Approval.

Spot 100' plug inside 8 5/8" cgs. opposite Top Salt.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael K. Heston TITLE Production Clerk DATE 9-29-78

APPROVED BY John Runyon TITLE Geologist DATE OCT 2 1978

CONDITIONS OF APPROVAL, IF ANY:  
\* Note above