NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C–102 and C–103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	_	
U.S.G.S.		5a. Indicate Type of Lease
		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		L-4632
(DO NOT USE THIS FORM FOR P USE "APPLIC	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS   WELL WELL   2. Name of Operator	OTHER- Dry Hole	7. Unit Agreement Name
Union Oil Company of California		8. Farm or Lease Name
3. Address of Operator		Cinch State
	VI 11 1 7 70700	9. Well No.
P. O. Box 671 -	Midland, Texas 79702	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER J	2310 FEET FROM THE South LINE AND 1650 FEET FROM	
	TION 19 TOWNSHIP 14 South RANGE 34 East.	
THE LINE, SEC		$\Delta M M M M M M M M M M M M M M M M M M M$
() () () () () () () () () () () () () (	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
16.	4152' GR.	Lea
Check NOTICE OF	Appropriate Box To Indicate Nature of Notice, Report or Of INTENTION TO: SUBSEQUEN	her Data T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER	OTHER	
17. Describe Proposed or Completed ( work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, including	g estimated date of starting any proposed
Drilled 7-7/8" hole 7-19-77. Ran electr	from 4,405' to 10,660' total depth. Reached tot ic logs.	al depth at 2:00 A.M.
PLUGGING PROCEDURE:		
	anded and Dive No. 1 10 ((0) a 10 f(0) and 0	
Shot Blue No. 2 10 2	ended, spot Plug No. 1 10,660' to 10,560' with 3	0 sx cement.
Spot Plug No. 2 10,381' to 10,281' with 30 sx cement.		
Spot Plug No. 3 7,994' to 7,894' with 30 sx cement.		
Spot Plug No. 4 5,979' to 5,879' with 30 sx cement.		
Spot Plug No. 5 4,429' to 4,231', in open hole and bottom of 8-5/8" OD Casing, with 55 sx.		
Spot Plug No. 6 1,980' to 1,800' with 50 sx cement.		
Spot Plug No. 7 at surface in 8-5/8" OD Casing from 20' to surface with 10 sx cement.		
Pump 9.5# mud between cement plugs. Weld $1/2"$ steel plate on surface casing. Install		
4" x 4' pipe dry hole	e marker, as per N.M.O.C.C. rules and regulation	S.
-		
Verbal approval to pl	lug and abandon, as shown above, obtained 7-20-7	7 from Mr. John Runvan
with the N.M.O.C.C.	office at Hobbs by 'phone by Mr. Julian White of	Union Oil Company of
California.		
$\bigcirc$		
18. I hereby certify that the information	n above is true and complete to the best of my knowledge and belief.	
( h. l	-	
Mitoutra -	J. R. Hughes TITLE District Drilling Supt.	T. 1. 00 1037
SIGNED HIMANAPIL		July 22, 1977
	Orig. Signed by	
•	Jerry Coston	
APPROVED BY	Dist i Supe TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY	** Expires 1/25/18	