N. M. OIL CONS. COM. Auto Form 31600EDENED P. O. BOX 1980 FORM APPROVED UNITED STATES HOBBS. NEW MEXICO 88240 Budget Bureau No. 1004-0135 3DEPARTMENT OF THE INTERIOR (June 1990) Expires: March 31, 1993 BUREAU OF LAND MANAGEMENT 5. Lease Designation and Serial No. NM 62235 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Oil Well 8. Well Name and No. X Other P&A Chambers ADX Federal #1 2. Name of Operator (505) 748-1471) 9. API Well No. YATES PETROLEUM CORPORATION 30-025-25061 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area 105 South 4th St., Artesia, NM 88210 East Morton Wolfcamp 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Unit B, 660' FNL & 1980' FEL, Sec. 33-T14S-R35E Lea, NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Notice of Intent New Construction Recompletion X Subsequent Report Plugging Back Non-Routine Fracturing Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* 4-21-93 - 4-29-93. Plugged well as follows: RUPU. Pulled rods and tubing. Set CIBP at 10300'. and cap with 35' cement. RIH w/tubing and loaded w/mud. Pulled tubing. Perforated casing at 8200', but could not pump into squeeze. Spot 35 sx cement plug at 8200'. Pulled tubing. Freepoint casing - free at 7400'. Cut casing at 7248'. Casing would not come loose. SD for weekend. Work casing, but could not pull. Shot again at 7141'. Pulled casing. Laid down 170 jts 5-1/2" casing. RIH w/tubing to 7248' and spot 35 sx cement plug. Pulled 25 stands and hung in derrick. WOC. RIH w/tubing. Tag plug at 7065'. Spot 48 sx cement plug at 6200'. Spot 25 sx plug at 4750'. WOC 4 hrs. Tag plug at 4624'. Andy Cortez, BLM, Carlsbad, NM, witnessed this tag. Spot 50 sx cement plug at 1975'. Pulled and laid down remainder of tubing. Spot 15 sacks surface plug. Set regulation abandonment marker. Plugging completed 4-29-93. Approved as to plugging of the well bore. Liability under bond is retained until surface rectoration is completed.

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements

Title Production Supervisor

14. I hereby certify that the foregoing is True and correct

or representations as to any matter within its jurisdiction.

4-30-93

JUN 15 1993

CONTROL VED

1 1 1 w

JUN 18 1993

- JABS