

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-25717

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

L-6881

7. Lease Name or Unit Agreement Name

State 16

8. Well No.

1

9. Pool name or Wildcat

Austin (Penn)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Adobe Resources Corporation

3. Address of Operator

300 West Texas, Suite 1100, Midland, TX 79701

4. Well Location

Unit Letter M : 660 Feet From The West Line and 990 Feet From The South Line

Section 16

Township

14-S

Range 36-E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3947 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up plugging unit. Unseat pump & lay down 7/8" & 3/4" rods. ND wellhead & NU BOP.
2. POOH with 2-3/8" tubing. PU overshot & GIH w/tbg. Fish RBP @ 11,400'. POOH w/tbg. LD RBP.
3. Set CIBP @ 13,000' w/20' cement on plug.
4. Set CIBP @ 11,100'. GIH w/2-3/8" tbg to 11,100'. Circ hole w/9.2# mud. Spot 10 sx Class "H" plug @ 11,100 to 11,012'.
5. Spot plugs as follows: 20 sx C1 "H" 9777 to 9853'.
20 sx C1 "H" 8443 to 8619'.
20 sx C1 "H" 7361 to 7537'.
70 sx C1 "H" 4432 to 5050'.
6. POOH w/tbg. FIH & free point 5-1/2" csg. Attempt cut @ 4400'. LD 5-1/2" csg GIH w/2-3/8" tbg to 4432'. Spot 45 sx C1 "H". Plug to 4300'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Lonnie Arnold

TITLE

Engineer

DATE

2/25/92

TYPE OR PRINT NAME

Lonnie Arnold

TELEPHONE NO. 915-683-4701

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER

2. Name of Operator

3. Address of Operator

4. Well Location

Unit Letter _____ : _____ Feet From The _____ Line and _____ Feet From The _____ Line

Section

Township

Range

NMPM

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: _____ ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: _____ ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7. Spot plugs as follows: 55 sx CL "H" 1950 to 2100'.
40 sx C1 "H" 318 to 418'.
10 sx C1 "H" surface

Perforation: 13,240-13,464'.
11,178-11,199'.

Formation tops: San Andres - 4600'.
Tubb - 7487'.
Abo - 8569'.
Wolfcamp - 9803'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: