

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-5087	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator MWJ PRODUCING COMPANY		8. Farm or Lease Name Saunders 28 State	
3. Address of Operator 1804 First National Bank Bldg Midland, Texas 79701		9. Well No. 1	
4. Location of Well UNIT LETTER <u>F</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or WHdcat Saunders Permo Upper Pen	
15. Elevation (Show whether DF, RT, GR, etc.) 4216.6' GL		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER Perf & acd ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

8/14/85: Pulled tbg. Ran SSN & 316 jts 2-3/8" Buttress Thread Tbg & tagged btm w/7' of 317th jt. Pulled & LD 317 jts tbg (SN @ 10000'). RU Dowell & spt'd 1000 gals 15% HCL ac. RD Dowell & POOH. RU CRC & perf'd "C" zone from 9964-9970' & 9992-9998' 2 SPF w/4" OD csg gun. Ran Baker Model R-3 pkr, SSN & 304 jts 2-3/8" tbg. SDON.

8/15/85: Ran 11 jts 2-3/8" tbg. Set pkr @ 9960' w/15000# tension. Pmpd 50 bbls 2% KCL wtr dn tbg, failed to load. Pulled 1 jt & set pkr # 9929' w/15000# tension. Swbd to test tank 4 hrs. RU Dowell & pmpd 2000 gals 20% HCL ac & flushed w/200 bbls 2% KCL wtr. Acd dn tbg w/1000 gals 20% HCL ac & 50 7/8" 1.1 sp grav BS @ 8 BPM @ 500 psi. Ball action to 3500 psi @ 5 BPM. Flushed w/45 bbls 2% KCL wtr. ISIP 0. Chk'd FL @ 400' & swbd to test tank 2 hrs, rec'd 49 BF, FL 4900'. CWI ON.

8/16/85: POOH, LD SN & pkr. Ran T/P, fl pac assy & drifted 209 jts tbg in hole. Set pkr w/7000# tension & flanged up. Ran 1" seal assy & vent string, no change. Landed w/8000# tension & packed it off. Pmpd 50 bbls 2% KCL wtr & dropped Std Vlv. Circ'd hole w/200 bbls 2% KCL wtr, press up to 2000 psi, OK. Bled off & SDON.

8/17/85: Rebuilt W/H. RD & MO.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pat Drexler

TITLE Pat Drexler - Agent

DATE 10/15/85

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE OCT 21 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
OCT 18 1985  
O.C.D.  
HOBBS OFFICE