

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER _____	7. Unit Agreement Name Duncan Unit
2. Name of Operator Harvey E. Yates Company	8. Form of Lease Name
3. Address of Operator Post Office Box 1933 Roswell, New Mexico 88201	9. Well No. 2
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 26 TOWNSHIP 13S RANGE 35E NEARBY _____	10. Field and Pool, or Wildcat Wildcat
11. Elevation (Show whether DF, RT, GR, etc.) 4019.6' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM ADDITIONAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐
OTHER _____

ALTERING CASING
PLUG AND ABANDONMENT

OTHER **Plug back and complete in Austin zone** ☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 7/25/81 1. Pull tubing and packer out of hole.
2. Trip in hole w/overshot to retrieve Vann tool guns.
- 7/27/81 3. Run CIBP and set on wireline @ 13,460'. Dump 35' of cement on top of CIBP.
4. Run Geo-Vann tubing conveyed gun assembly to perforate Austin zone w/4 JSPF from 13,404' to 13,419'. Total 60 1/2" diameter holes.
- 7/29/81 5. Flow test well.
6. Acidize, if necessary. Swab and flow test.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Engineer

DATE

July 24, 1981

APPROVED BY

TITLE

DATE

JUL 27 1981

CONDITIONS OF APPROVAL