



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

RY E. JOHNSON
Governor
Salfer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

DATE: May 6, 2002

Company Name: Marks & Garner Production, LTD. Co.
Address: PO Box 70
City, State, Zip, and Phone: Lovington NM 88260

Form C-103, Report of Plugging for your: Saunders 28 A State #1-H (28-14s-33e)

Can not be approved until a Division representative has made an inspection of the location and found it to be in compliance of Division Rule and Regulations. Please check each item in the space provided to indicate that the work has been done.

- 1. All pits have been remediated in compliance with Division "Pit Remediation Guidelines".
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It must show the OPERATOR NAME, LEASE NAME, WELL NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE.
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and pit location(s) have been remediated to Division "Pit Remediation Guidelines" and all flowlines, production equipment and junk removed from lease or well location.

The above are minimum requirements and no plugging bond will be released until all locations for plugged and abandoned wells have been inspected and Form C-103 approved. When all of the work outlined above has been done, please notify this office by filling in the blank form below and returning this letter to us so a Division representative will not have to make more than one trip to a location.

Sincerely,
OIL CONSERVATION DIVISION
Chris Williams
Chris Williams, District I Supervisor

FILL IN BELOW AND RETURN TO: Oil Conservation Division, 1625 N. French Drive, Hobbs, NM 88240
I certify that the above work has been done and the well or lease referenced above is ready for inspection and approval.

**MARKS AND GARNER
PRODUCTION LTD. CO.**
P.O. BOX 70
LOVINGTON, NM 88260

<i>[Signature]</i>	<i>[Signature]</i>	505-596-5320
NAME & TITLE	DATE	PHONE

RECEIVED
Hobbs
OCD
JUN 11 2002

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-27361

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

L-5087

7. Lease Name or Unit Agreement Name

SAUNDERS 28 "A" STATE

8. Well No.

1

9. Pool name or Wildcat

SAUNDERS PERMO UPPER PENN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

MARKS AND GARNER PRODUCTION, LTD. CO.

3. Address of Operator

P O Box 70 LOVINGTON NM 88260

4. Well Location

Unit Letter : H : 660 Feet From The EAST Line and 1980 Feet From The NORTH Line

Section 28 Township 14S Range 33E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4206.5

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET CIBP 9700' WITH 25 SACKS CEMENT ON TOP
LOAD HOLE WITH 10# BRINE W/ 25 SACKS GEL
SHOOT & PULL @ 8300'
SPOT 50 SACKS CEMENT IN & OUT OF STUB
SPOT 50 SACKS @ 5800'
SPOT 50 SACKS CEMENT @ 4125 IN & OUT
SPOT 50 SACKS 370'
10 SACK PLUG AT SURFACE-INSTALL DRY HOLE MARKER

Set 100 plug @ top salt 1650

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

James H. Buddy Garner

TITLE Partner

DATE 8-1-96

TYPE OR PRINT NAME

James H. Buddy Garner

TELEPHONE NO. 396-5326

(This space for State Use)

AUG 01 1996

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: