STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

DISTRICT I SUPERVISOR

OIL CONSERVATION DIVISION

1983

SANTA FE, NEW MEXICO 87501	Revised 19-1-1	
FILE	5a. Indicate Type of Leise	
U.S.G.S.	State Then X	
LAND OFFICE	S. Sente Off & Gan Lease No.	
OPERATOR		
	Land Company	
SUNDRY NOTICES AND REPORTS ON WELLS		
IDS NOT USE THIS FORM FOR PROPOSACS TO DRILL OR TO DECEPT ON PLOT BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT = " (FORM C-101) FOR SHOPOSACS.)	2. Unit An ecment Name	
1. 91. [3] 6A8 [7]	7. Cult Advecment Name	
WELL OTHER-		
2. Name of Operator	8. Farm of Lease flame	
Anadarko Porduction Company	Byars	
.), Address of Operator	9, Well No.	
P.O. Box 806 Eurice, New Mexico 88231	1	
P. O. BOX 806 EUNICE, NEW MEXICO 88231	to Floid and Post, or Window	
1		
WHIT LETTER A 660 PERT FROM THE NORth LINE AND 660 FEET FROM	" tere en reen en en en en en en en	
THE East LINE, SECTION 8 TOWNSHIP 128 RANGE 38E		
15. Elevation (Show whether OF, RT, GR, etc.)	12. County	
3861.7 GR	Lea	
	in to come or communication and the state of	
Check Appropriate Box To Indicate Nature of Notice, Report or Oc		
NOTICE OF INTENTION TO: SUBSEQUEN	IT REPORT OF:	
	_	
PERFORM REMEDIAL WORK	ALTHRING CASING	
TEMPORARILY ASANDON COMMENCE DESILLING GPHS,	PLUG AND ABANDONMENT	
PULL OR ALTER CASING TEST AND CEMENT JOB	C	
OTHER Personated Atolic	a Zano 🕏	
The transfer of the transfer o	1	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dutes, includin	g estimated date of starting any propos	
work) SEE RULE 1703.		
1. RUPU. TOH w/2-7/8" tbg.		
2. RU Welex. Ran wireline cement retainer & set (1 11,980'. TIH w/ceme)	nt retainer stinger	
on 2-7/8" tbq.		
3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o	about 3 sx dumped	
3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o	about 3 sx dumped owly. TIH w/tba.	
3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl	about 3 sx dumped owly. TIH w/tbg.	
3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer.	owly. TIH w/tbg.	
 3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. 4. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 1 	owly. TIH w/tbg. 1,960'.	
 3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. 4. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 1 5. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to	
 3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. 4. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 1 5. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on tog. Tried to break down 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500	
 3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of hetainer. 4. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 1 5. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on tog. Tried to break down gals, 7½ Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on tog. Tried to break down gals, 7½ Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on *bg. Tried to break down gals, 7½ Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per-	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on tog. Tried to break down gals, 7½ Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per-	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on *bg. Tried to break down gals, 7½ Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per-	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on *bg. Tried to break down gals, 7½% Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to formation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on *bg. Tried to break down gals, 7½8 Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. RU Dresser Titan. Acidized w/1500 gals 7½% HCL & 1½% Hydro-Floric 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to formation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15 Acid. Formation	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on *bg. Tried to break down gals, 7½% Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. RU Dresser Titan. Acidized w/1500 gals 7½% HCL & 1½% Hydro-Floric broke @ 2400# PSI. AIR&P was 2½ BPM @ 2600#. Max press 3000#. Flus 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to formation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15 Acid. Formation hed w/66 bbls	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on *bg. Tried to break down gals, 7½ Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. RU Dresser Titan. Acidized w/1500 gals 7½ HCL & 1½ Hydro-Floric broke @ 2400# PSI. AIR&P was 2½ BPM @ 2600#. Max press 3000#. Flus 2% KCL fluid. ISIP 2600# PSI, 5 min SI 2400#, 15 min SI 2100# PSI. 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15 Acid. Formation hed w/66 bbls	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on "bg. Tried to break down gals, 7½8 Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. RU Dresser Titan. Acidized w/1500 gals 7½8 HCL & 1½8 Hydro-Floric broke @ 2400# PSI. AIR&P was 2½ BPM @ 2600#. Max press 3000#. Flus 2% KCL fluid. ISIP 2600# PSI, 5 min SI 2400#, 15 min SI 2100# PSI. RU to swab. Swabbed 1 BO & 35 BLW in & hrs w/only trace of gas flu 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15 Acid. Formation hed w/66 bbls	
 RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on "bg. Tried to break down gals, 7½8 Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. RU Dresser Titan. Acidized w/1500 gals 7½8 HCL & 1½8 Hydro-Floric broke @ 2400# PSI. AIR&P was 2½ BPM @ 2600#. Max press 3000#. Flus 2% KCL fluid. ISIP 2600# PSI, 5 min SI 2400#, 15 min SI 2100# PSI. RU to swab. Swabbed 1 BO & 35 BLW in & hrs w/only trace of gas flu 	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15 Acid. Formation hed w/66 bbls	
3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. 4. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on *bg. Tried to break down gals, 7½8 Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. 6. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. 7. RU Dresser Titan. Acidized w/1500 gals 7½% HCL & 1½% Hydro-Floric broke @ 2400# PSI. AIR&P was 2½ BPM @ 2600#. Max press 3000#. Flus 2% KCL fluid. ISIP 2600# PSI, 5 min SI 2400#, 15 min SI 2100# PSI. 8. RU to swab. Swabbed 1 BO & 35 BLW in 8 hrs w/only trace of gas flue @ b bbl per hr	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15 Acid. Formation hed w/66 bbls uid entry into well	
3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. 4. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on "bg. Tried to break down gals, 7½ Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. 6. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. 7. RU Dresser Titan. Acidized w/1500 gals 7½ HCL & 1½ Hydro-Floric broke @ 2400# PSI. AIR&P was 2½ BPM @ 2600#. Max press 3000#. Flus 2% KCL fluid. ISIP 2600# PSI, 5 min SI 2400#, 15 min SI 2100# PSI. 8. RU to swab. Swabbed 1 BO & 35 BLW in 8 hrs w/only trace of gas flug be belowed to be the best of me snowledge and belief. 9. Closed well in. RDPU.	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15 Acid. Formation hed w/66 bbls	
3. RU Halliburton. Squeezed Devonian zone w/50 sx Class "H" cement w/o on top of retainer. Pressured up on cement retainer. Leaked off sl Couldn't find cement on top of retainer. 4. RU Welex. Set CIBP @ 11,979' w/19' cement on top of B.P. PBTD @ 15. TIH w/ Baker Lok Set PKR w/Geo-Vann Gun System. Tried to perforate 11,275'. Dropped bar, had slight blow on *bg. Tried to break down gals, 7½8 Hydro-Floric Acid. Wouldn't break w/3500#. TOH w/tbg. Fo & dropped to bottom & 1 jt. tbg had collapsed. 6. Re-ran Baker Loc Set PKR w/Geo-Vann Gun System. Set PKR @ 11,233'. forated Atoka @ 11,263' - 11,275' w/4 JSPF, ½" holes. Had weak blo min. 7. RU Dresser Titan. Acidized w/1500 gals 7½8 HCL & 1½8 Hydro-Floric broke @ 2400# PSI. AIR&P was 2½ BPM @ 2600#. Max press 3000#. Flus 2% KCL fluid. ISIP 2600# PSI, 5 min SI 2400#, 15 min SI 2100# PSI. RU to swab. Swabbed 1 BO & 35 BLW in 8 hrs w/only trace of gas flue @ 2 bbl per hr. 18. I horeby cently that the information above is true and complete to the best of my knowledge and belief. 9. Closed well in. RDPU.	owly. TIH w/tbg. 1,960'. Atoka @ 11,263'to Kormation w/ 1500 und guns had parted Dropped bar. Per- w which died in 15 Acid. Formation hed w/66 bbls uid entry into well	

RECEIVED

JUN' 3 1983

HOBES UNILE