

UNIT	
DISTRICT	
SANTA FE	
FILE	
U.S.C.S.	
LAND OFFICE	
OPERATOR	

1. Indicate Type of Lease
State ☐ Fee ☒
2. State Oil & Gas Lease No.
18895

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT WITH FORM C-1011 FOR SUCH PROPOSALS.)OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name

8. Farm or Lease Name

Stevens

9. Well No.

1

10. Field and Pool, or Wildcat

Tulka (Penn)

12. County

Lea

15. Elevation (Show whether DF, RT, CR, etc.)

4287.9 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 6/1/82: MI PBCP to start plugging operations.
- 6/2/82: RU & pulled tbq & pkr. Change out sd line & set CIBP @ 8900'. Dumped 5 sx (35') cmt on top.
- 6/3/82: GIH w/tbg to 7000' & displaced hole w/mud ladden fluid.
- 6/4/82: RU to pull 5½" csg. Pulled slips out, tired to shoot off @ 8500', charge did not go off.
- 6/5/82: Tried to shoot off @ 7000', could not. SD ON.
- 6/6/82: SD for Sunday.
- 6/7/82: Shot off @ 6986', csg would not move. Pressure up to 2200 psi, wouldn't move. Shot off @ 6464' & pressured up to 2000 psi w/180000# pull, could not move.
- 6/8/82: Shot off @ 6000', didn't move. Tried @ 5800', same, tried at 5500', same.
- 6/9/82: Shot off @ 5200' & was able to get loose. Pmpd around csg. Pulled & LD 126 jts 5½" csg. Ran tbq to 5600'. Set 50 sx cement plug @ 5530'. Set stub plug @ 5250' & pmpd 35 sx cmt.
- 6/10/82: Tagged plug & pulled back up. Set 35 sx cement plug @ 4070'.
- 6/11/82: Tagged plug & set 35 sx cement plug from 1450-1550'. Cut off Wellhead & set 10 sx cement plug at surface. Installed Dry Hole Marker. RD & MO. WELL P & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don Bishop TITLE Agent DATE 6/14/82APPROVED BY Ronald M. Castleberry TITLE OIL & GAS INSPECTOR DATE JAN 24 1983

CONDITIONS OF APPROVAL, IF ANY