

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27715
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG - 8382
7. Lease Name or Unit Agreement Name STATE 10C
8. Well No. 1
9. Pool name or Wildcat WILDCAT

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DRY	
2. Name of Operator NEARBURG PRODUCING COMPANY	
3. Address of Operator P.O. BOX 31405, DALLAS, TEXAS 75231-0405	
4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 10 Township 12S Range 38E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3851' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: START RE-ENTRY <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-30-89: Drilled surface plug. Test BOP's and casing to 2000#.

3-31-89: Drilled plugs from 2250-2400', 4415-4515', 5900-6000', 7900-8200'. Cleaned out to 8600'.

4-01-89: Spotted 225 sacks of Class "H" @ 8500'. W.O.C.

4-02-89: Tagged cement @ 8220'. Dressed off top of plug to 8272'. Picked up down hole motor and bent sub. Oriented tools, started drilling 7-7/8" hole.

5-02-89: Reached T.D. of 12,400'

5-03-89: Ran open hole logs. Logs indicate well non-productive. Called NMOC for plugging instructions.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Eddie J. Gelwick TITLE Operations Coordinator DATE 6/16/89
TYPE OR PRINT NAME EDDIE J. GELWICK TELEPHONE NO. 214/739-1778

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUN 19 1989