

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☒ Fee ☐
3. State Oil & Gas Lease No.
NM V-128

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPLY OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator MWJ PRODUCING COMPANY	8. Farm or Lease Name Baum 17 "A" State
3. Address of Operator 1804 First National Bank Bldg. Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER K 1980 FEET FROM THE west LINE AND 1980 FEET FROM THE south LINE, SECTION 17 TOWNSHIP 14S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Baum Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4251' GL.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	Perf, acd & swb test

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop work) SEE RULE 1103.

11/18/82: MI & RU Swbg Unit. Found FL @ 4000' FS. Made 6 swab runs, rec'd 21 BF, trace of oil, show of gas. RD & MO.

12/6/82: MI & RU PU. Released pkr & loaded hole w/110 bbls 2% KCL wtr. Ran 4 jts tbg w/tb @ 9968'. Sptd 1000 gal 20% HCL ac. Pulled & LD 4 jts. Pulled addt'l 112 jts & SD ON.

12/7/82: Pulled 190 jts, changeover, std SN & Baker R-3 pkr. RU CRC & perf'd "B" zone as follows: 9933-9935, 9940-9945' & 9956-9958' (2 SPF) w/.4" OD csg gun. RD CRC. Ran Baker R-3 pkr, std SN, changeover & 302 jts tbg. Dowell rev'd ac back in tbg. Set pkr @ 9938.99' w/15000 & flanged up. PT csg to 1600 psi. Acd @ 1.2 BPM @ 6200 psi w/24 BFW. ISIP 5900 psi, 10 min 5500 psi. Bled off & rec'd 4 BF. CWI O

12/8/82: Started swbg. FL @ 5500'. Made 10 swab runs, rec'd no oil w/slight gas. SD due to bad weather.

12/9-10: SD due to bad weather.

12/11/82: Swbd 5 hrs, rec'd 25 BF, no oil or gas. IFL 4400', FFL 5500'. Released swbg unit Waiting to Plug & Abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Agent DATE 12/27/82
ORIGINAL SIGNED BY
JERRY SEXTON
DISTRICT 1 SUPR.
APPROVED BY _____ TITLE _____ DATE DEC 30 1982
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
DEC 29 1982
C. D.
HOLBS OFFICE