State of New Mexico Energy, Mine and Natural Resources Department

Form C-103 Revised 1-1-89

10 1 thbrohiters	
District	A 55:
CHZILLEL	Ottice

DISTRICT I OIL CONSERVATION DIVISIO	N		
P.O. Box 1980, Hobbs, NM 88241-1980 2040 South Pacheco	WELL API NO.		
Santa Fe. New Mexico 87505			
811 S. First Street, Artesia, NM 88210	5. Indicate Type of Lease  STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec. NM 87410	6. State Oil & Gas Lease No. K-4670		
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK 'DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	TO A 7. Lease Name or Unit Agreement Name		
I. Type of Well:			
OIL GAS WELL OTHER	STATE DY		
Name of Operator	8. Well No.		
ELK OIL COMPANY	1		
3. Address of Operator	9. Pool Name or Wildcat		
POST OFFICE BOX 310, ROSWELL. NEW MEXICO 88	202-0310 BAUM UPPER PENN		
4. Well Location	1000		
Unit Letter K : 1953 Feet From The WEST L	ine and 1980 Feet From The SOUTH Line		
Section 19 Township 13 SOUTH Ran	ge 33 EAST NMPM LEA County		
10. Elevation (Show whether DF, RKB, RT	. GR, etc.)		
4292.8' GR			
11. Check Appropriate Box to Indicate Nature NOTICE OF INTENTION TO:	·		
NOTICE OF INTENTION TO.	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON R	EMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS	OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING CA	ASING TEST AND CEMENT JOB		
OTHER:	THER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103			
03/31/97: SET CIBP @ 9550', 25 SXS ON TOP, 9350'.			
04/02/97: SPOT 25 SXS @ 6550'-6350'.			
04/02/97: SPOT 25 SXS @ 4040'-3840'.			
04/04/97: SPOT 35 SXS @ 2150'-1800' PERFORATED @ 2100' COULD NOT PUMP INTO PERFS.			
PERFORATED @ 1900' COU	ILD NOT PUMP INTO PERFS.		
04/04/97: SPOT 45 SXS @ 1550'-1463' TAGGED - PULLED 1500' OF 5 1/2" CASING.			
04/04/97: SPOT 10 SXS @ 30' - SURFACE.			
INSTALL DRY HOLE MARKER.			
CIRCULATE HOLE WITH 10# MUD.			
LOCATION CLEANED AND READY FOR INSPECTION.			
Thereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE PRESIDE	ENT DATE 02/10/98		
TYPE OR PRINT NAME JOSEPH J. KELLY	TELEPHONE NO. 505-623-3190		
APPROVED BY JACK GAS STORE TER 23 TOTAL APPROVED BY JACK GAS STORE TER 23 TOTAL APPROVED BY			
APPROVED BY Jack Sriffin THE CONDITIONS OF APPROVAL, IF ANY:	LA GAS MSPECTOR DATE FEB 23 1993		