STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| | 11416 |
|------|-------|
| | |
| 1 | |
| 1 | |
| abla | |
| T | |
| | |
| | |
| | |

IL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

JUN 1 9 1986

| SANTA FE | | SANTA FE, NEW MEXICO 87501 | | | | Revised 10-1 | | |
|--|--|--|---|---|--|--|--|--|
| FILE | | _ | | | Sa. Indicate | e Type of Lease | | |
| U.S.O.S. | | _ | | | State | | | |
| DERATOR | - | | | | | 1 & Gas Lease No. | | |
| | | - -J | | | | | | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO OFFILE OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) | | | | | | | | |
| OIL X | 7. Unit Agr | 7. Unit Agreement Name | | | | | | |
| Sun Exploration & Production Company | | | | | | New Mexico JJ State | | |
| P.O. Box 1861 Midland, Texas 79702 | | | | | | 9. Well No. | | |
| 4. Location of Well | | | | | 10, Field o | and Pool, or Wildcat | | |
| UNIT LETTER G, 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM | | | | | | Baum (Upper Penn) | | |
| THE East | LINE, SEC | TION | шинанір <u>135</u> | RANGE 32E | NMPM. | | | |
| | TITITITI. | 15. Elevat | Ion (Show whether | DF, RT, GR, esc.) | 12. County | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | |
| | | | | | Lea | | | |
| 16. | Check | Appropriate Box | To Indicate N | lature of Notice, Report | or Other Data | | | |
| - | | INTENTION TO: | | · | UENT REPORT | OF: | | |
| PERFORM REMEDIAL | WORK | PLUG | AND ABANDON | REMEDIAL WORK | <u> </u> | ALTERING CASING | | |
| TEMPORARILY ABAND | ON | | | COMMENCE DRILLING OPNS. | | PLUG AND ABANDONMENT | | |
| PULL OR ALTER CASI | NG | CHARG | E PLANS | CASING TEST AND CEMENT JOB | | _ | | |
| | | | <u></u> | OTHER | | | | |
| OTHER | | | | | | | | |
| 17. Describe Propos work) SEE RUL | | Operations (Clearly state | e all pertinent det | ails, and give pertinent dates, inc | cluding estimated do | ite of starting any propos | | |
| 5/13/86 | w/350 bb1 | | to circ/ o | se TAC lower tbg tag Irop SV test tbg 4000 | | | | |
| 5/14/86 | | Finish POH/RIH w/4-3/4 RB 8-3½ DC on 2-7/8 (L-80) tbg to 9710/NU foam equip/foam air pump 4 hrs unable to unload fluid | | | | | | |
| 5/15/86 | PU to 8645' foam air unload hole w/foam 1wr to cmt retainer at 9840' broke circ drlg cmt retainer # cmt from 9840' to 9858' 1 wr to PBTD of 9906' circ clean w/foam POH to 2108' | | | | | | | |
| 5/16/85 | 2 JSPF 31 w/BJs PFT trip PFT | holes w/4" csg on 2-7/8 tbg r thru perf 9735- | gun 23 gir cound trip f 9858 pumpir | / Schlum perf 9833-98 n 34 EH by DA GR-CN-L PFT thru perfs 9735-9 ng 1500 gal 15% NEFE/ H w/5½ RDB pkr on 2-7 | .D dated 9-30 9858 pumping 'AIR 2 BPM Ma | 0-83/ RIH 2% KCL round ax TP 1080 csg | | |
| | | | | | • | · | | |
| 18. I hereby certify | that the informatio | on above is true and com | plete to the best of | I my knowledge and belief. | | | | |
| | \wedge | /\ | | - | | | | |
| 1/08 | Thom L | son h | · TITLE AC | sociate Accountant | | 6/12/86 | | |

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR