

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6444	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Hanladdie WR State
Address of Operator 207 South 4th St., Artesia, NM 88210		9. Well No. 3
Location of Well UNIT LETTER <u>F</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Saunders Permo Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4221.2' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

Perforate & treat additional Permo Penn ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Moved in and rigged up pulling unit. TOOH w/pump and rods. WIH and perforated 9777-9868' w/14 .50" holes as follows: 9777, 78, 83, 84, 9806, 07, 23, 24, 37, 38, 62, 63, 67 and 68'. TIH w/bridge plug, packer and tubing. Acidized perfs 9777-9868' w/8000 gal 15% NEFE acid and ball sealers. TOOH w/packer, bridge plug and tubing. Set pumping equipment. Return well to production producing from perforations 9914-45' and 9777-9868'.

3. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHECKED [Signature] TITLE Production Supervisor DATE 8-15-84

ORIGINAL SIGNED BY JERRY SEXTON

PROVED BY DISTRICT 1 SUPERVISOR TITLE DATE AUG 17 1984

CONDITIONS OF APPROVAL, IF ANY: