

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28394
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	State of NM "T"
8. Well No.	5
9. Pool name or Wildcat	Baum Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4235'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	2. Name of Operator Louis Dreyfus Natural Gas
3. Address of Operator 14000 Quail Springs Parkway, Ste. 600, Oklahoma City, OK	4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 4 Township 14S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4235'	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) 7-13-01 Set 5-1/2 CIBP @ 9665' w/ 4 sx cmt. 35' on top the CIBP.
- (2) 7-16-01 Circulation w/ mud gel.
- (3) 7-17-01 Cut 5-1/2 Casing @ 6650', spot 25 sx cmt. from 6700 to 6570, tag @ 6580'.
- (4) 7-18-01 Spot 30 sx cmt. from 4150 - 4050, 8-5/8 shoe, WOC & tag @ 4038'.
- (5) 7-18-01 Spot 30 sx cmt. from 1740 to 1640', no tag.
- (6) 7-18-01 Spot 30 sx cmt. from 470 to 370, WOC & tag @ 355'.
- (7) 7-18-01 Spot 15 sx cmt. from 50' to 3', surface plug.
- (8) Cut csg., welded on plate, erected steel marker, cleaned location.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 7/24/01

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] DATE _____

CONDITIONS OF APPROVAL, IF ANY:

GWN

CC FIELD REPRESENTATIVE II/STAFF MANAGER

JAN 16 2003

