

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28416
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LG-3224
7. Lease Name or Unit Agreement Name Lea "VF" State
8. Well No. 3
9. Pool name or Wildcat Saunders Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Manzano Oil Corporation 505/623-1996	3. Address of Operator P.O. Box 2107/Roswell, NM 88202-2107
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>14 South</u> Range <u>33 East</u> NMPM Lea County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4220.7' GL		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/06/95 Notified Bonnie w/OCD on MI & RUPU. RUWL. Ran & set 5-1/2" CIBP @ 9191'. RIH w/2-3/8" tbq. Tag CIBP.
4/07/95 Notified Jack G. w/OCD on CIBP setting. Tag CIBP w/tbg. POOH. RUWL. Ran & dump bail 5 sx cmt on top CIBP @ 9191'. Ran & set 5-1/2" CIBP @ 8891'. Dump bail 5 sx cmt on top. RDWL.
4/10/95 Spot 130 bbl plug mud from 8800-3000' in 5-1/2" csg. M&P 25 sx Cl C cmt from 6800-6600' in 5-1/2" csg. POOH w/2-3/8" tbq to 4300'. M&P 25 sx Cl C cmt from 4300-4100' in 5-1/2" csg. RUWL. Ran & cut 5-1/2" csg @ 3000'. RDWL. POOH & LD 76 jts 5-1/2" csg.
4/11/95 Notified Jack Griffin w/OCD on cmt plugs. M&P 30 sx Cl C cmt w/2% CaCl from 3050' in 5-1/2" csg to 2950' in 8-5/8" csg. Tag TOC @ 2900'. Spot 180 bbl plug mud from 2890-surf. M&P 35 sx Cl C cmt from 2200-2100' in 8-5/8" csg. M&P 10 sx Cl C cmt from 30'-surf. PU clean loc. P&A complete 4/11/95. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Hernandez TITLE Engineering Technician DATE 11/14/95
TYPE OR PRINT NAME Allison Hernandez TELEPHONE NO. 505/623-199

(This space for Sign Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28416
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LG-3224
7. Lease Name or Unit Agreement Name Lea "VF" State
8. Well No. 3
9. Pool name or Wildcat Saunders Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Manzano Oil Corporation 505/623-1996	
3. Address of Operator P.O. Box 2107/Roswell, NM 88202-2107	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>14 South</u> Range <u>33 East</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4220.7' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
PLUG AND ABANDON ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 9780' + 10 sks cement plug on top.
2. Set 25 sks plug @ 6800-6700'.
3. Cut 5-1/2" csg @ 4200'. Spot 35 sks plug from 4300-4150'.
4. Set 35 cks plug from 2200-2100'.
5. Set 10 sks surface plug.
6. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Raney TITLE Engineering Technician DATE 12/02/93
TYPE OR PRINT NAME Allison Raney TELEPHONE NO. 505/623-1996

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 06 1993