

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-778

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - D" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TXO Production Corp.	8. Farm or Lease Name Cone State Comm
3. Address of Operator 900 Wilco Bldg, Midland TX, 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>14-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat High Plains Pennsylvanian
15. Elevation (Show whether DF, RT, GR, etc.) 4098.0 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed plugging procedure:

CIBP @ 10,300 w/35' cmt
100' cmt@ cut off of 5 1/2" csg (est @ 9800')
100' cmt 8050-8150' (top of Abo)
100' cmt 5650-5750' (top of Glorietta)
100' cmt 4650-4550' (8 5/8" csg shoe)
100' cmt 1700-1800' (top of evaporites)
10 sx @ surface

***Add Plugs as Follows:

100' plug inside 8 5/8" at 13 3/8" shoe @ 418'
Load hole w/10# Salt Gel
Tag stub plug & shoe plug

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
DRILLING OPERATIONS FOR THE C-103
TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay TITLE Drilling Engineer DATE 2-21-84

APPROVED BY Eddie W. Seay TITLE Oil & Gas Inspector DATE FEB 28 1984

CONDITIONS OF APPROVAL, IF ANY:

***SEE ABOVE