

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-28486
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG 1623
7. Lease Name or Unit Agreement Name	
Raven YH State	
8. Well No.	1
9. Pool name or Wildcat	Tulk Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4315.2' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter <u>P</u> : <u>560</u> Feet From The <u>South</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>14S</u> Range <u>32E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4315.2' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-5-95 - Moved in and rigged up pulling unit. Pulled rods and pump. Nippled down wellhead. Rigged up tubing equipment. Unset tubing anchors. POOH with tubing. Rigged up wireline. RIH w/5-1/2" CIBP and set at 9650'. Dumped 35' of cement on top of CIBP.

1-6-95 - Shut down for day.

1-7-9-95 - RIH w/tubing. Loaded hole with mud. POOH with tubing. Dug out cellar. Nippled down wellhead. Welded onto 5-1/2" casing. Rigged up casing jacks. Pulled 5-1/2" wellhead slips. Took casing stretch. Casing stuck at 4400'. Worked casing. Restretch casing. Shows free at 5200'. Rigged up wireline and 5-1/2" cutter. RIH and cut casing at 5182'. Pulled 225000#. Worked casing, casing stuck. Restretched casing. Shows stuck at 4700'. Rigged up wireline and 5-1/2" cutter. RIH and cut casing at 4661'. Casing free. Rigged down casing jacks. Shut down for weekend.

1-10-95 - Rigged up casing equipment. Pulled and laid down 27 joints of 5-1/2" casing. Shut down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 1-13-95
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

OIL & GAS INSPECTOR

MAR 14 1995

DATE

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-28486

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG 1623

7. Lease Name or Unit Agreement Name

Raven YH State

8. Well No.

1

9. Pool name or Wildcat

Tulka Penn

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil
WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter P : 560 Feet From The South Line and 560 Feet From The East Line

Section

33

Township

14S

Range

32E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4315.2' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-11-95 - Finished laying down 5-1/2" casing. Rigged down casing equipment. Rigged up tubing equipment. RIH w/tubing to 7000'. Spotted a 25 sack cement plug at 7000'. Pulled up to 5550'. Spotted a 50 sack cement plug at 5550'. Covered 1 cut on 5-1/2" casing at 5182'. Pulled up to 4711'. Spotted a 25 sack cement plug across 5-1/2" cut off. Shut down.

1-12-95 - Tagged 5-1/2" stub plug at 4618'. Pulled up to 8-5/8" shoe at 4250'. Spotted a 25 sack cement plug. WOC. RIH and tagged plug at 4143'. Pulled to 1535'. Spotted a 25 sack cement plug. Set a 10 sack cement plug at surface. Cut wellhead off. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 1-11-95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE

Production Clerk

DATE 1-13-95

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State Use)

APPROVED BY

Jack Griffin

TITLE

DATE

MAR 14 1995

RECEIVED

JAN 17 1985
C. D. HOBBS
OFFICE