

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

RECEIVED BY
OCT 03 1984
O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name State QF 32	
9. Well No. 1	
10. Field and Pool, or Wildcat Wildcat	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator
Tenneco Oil Company

3. Address of Operator
7990 IH 10 West, San Antonio, Texas 78230

4. Location of Well
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 32 TOWNSHIP 12S RANGE 33E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4275.4 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Drill 7 7/8" hole to 4710'.
Ran DST with no oil recovery.
Plugged and abandoned well as follows:
Set bottom plug 3779'-3573' w/100 sxs Class -C.
Set top plug 1772'-1478' w/75 sxs Class -C + 2% CaCl₂.
Hole full of 10.2 ppg mud. Had good returns while spotting both plugs left 1,634' of 8 5/8" csg. in hole.
Set 10' surface plug w/5 sxs cement.
Remove head, weld on plate and dry hole marker.
P & A operations started and completed 8/6/84

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Div. Drilling Superintendent DATE 9/26/84

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE FEB 25 1987

CONDITIONS OF APPROVAL, IF ANY: