

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 2414
7. Unit Agreement Name
8. Farm or Lease Name Chalupa AAD State
9. Well No. 1
10. Field and Pool, or Wildcat Saunders Permo Upper Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Name of Operator Yates Petroleum Corporation
2. Address of Operator 207 South 4th St., Artesia, NM 88210
3. Location of Well UNIT LETTER <u>E</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM <u>West</u> THE <u>13</u> LINE, SECTION <u>14S</u> TOWNSHIP <u>33E</u> RANGE <u>NMPM.</u>
15. Elevation (Show whether DF, RT, GR, etc.) 4181.3' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Perforate & Treat

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in and RUPU. POOH w/pump, rods and tubing. WIH and perforated 9934-60' w/10 .42" holes as follows: 9934, 35, 36, 43, 46, 47, 48, 58, 59 and 60'.
Acidized perfs 9934-60' w/1500 gals 20% NEFE acid and ball sealers. Swab well and tested.
WIH and perforated 9995-98' w/5 .42" holes. Acidized perfs 9995-98' w/1000 gals 15% NEFE acid and ball sealers.
Swabbed well down.
Hung well on pump. Well producing from perforations 9821-92'; 9934-60' and 9995-98'.
Work completed 4-11-85.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed <u>Jerry Sexton</u>	TITLE <u>Production Supervisor</u>	DATE <u>4-15-85</u>
ORIGINAL SIGNED BY JERRY SEXTON		
DISTRICT 1 SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>APR 17 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 16 1985

O.C.C.
HOBBS OFFICE