

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

V-267

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL GAS
WELL ☒ WELL ☐ OTHER

2. Name of Operator
Read & Stevens, Inc.

3. Address of Operator
P.O. Box 1518, Roswell, NM 88201

4. Location of Well

UNIT LETTER E . 1830 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE. SECTION 27 TOWNSHIP 14S RANGE 34E NMPM

7. Unit Agreement Name

8. Farm or Lease Name
VALLIE STATE

9. Well No.
1

10. Field and Pool, or Wildcat

Und. Tres Papalotes Penn

5. Elevation (Show whether DF, RT, GR, etc.)
4112.2' GL

12. County
Lea

XXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-14-85 TD. P&A. Tear down rig. 2hrs PU pipe to 10,390', 12 1/2hrs plugging & LD DP, 4hrs circ, 1/2hr tag plug. Release rig @ 12:00midnight 1/13/85. Spotted plugs as follows:

10,390'-10,290'	40sx Class "H"
9721'-9621'	50sx Class "H"
8120'-8020'	40sx Class "C"
7382'-7282'	40sx Class "C"
5985'-5885'	40sx Class "C"
4580'-4480'	40sx Class "C" Tagged plug @ 4483', set 10,000#.
1900'-1800'	35sx Class "C"

WO surface plug & marker.

1-17-85 Move rig off hole. Spot 15sx surface plug w/dry hole marker, prep to clean loc.

1-18-85 Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. J. Hobbs TITLE Drilling and Production Manager DATE 2-14-85

APPROVED BY Edie W. Seely
CONDITIONS OF APPROVAL, IF ANY:
Oil & Gas Inspector

TITLE _____ DATE JAN 27 1986

RECEIVED

Aug 15 1985

U.S. DEPT. OF JUSTICE
ADJUTANT GENERAL