

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-29081

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

LG-3818

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER P & A Well

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210

7. Lease Name or Unit Agreement Name

Pyro ABK State

8. Well No.

1

9. Pool name or Wildcat

Lazy J Penn

4. Well Location

Unit Letter B : 660 Feet From The North Line and 1980 Feet From The East Line

Section 33

Township 13S

Range 33E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4243.5' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well as follows: Plugging began on June 14, 1993.

TOOH w/tubing and tubing anchor catcher. TIH and tagged at 9574'. Circulated hole with 10# gel mud. Laid down 55 joints. Spot 30 sack Class "C" 2% CaCl2 plug from 7900-7600'. POOH with 20 stands. WOC 2 hours. TIH and tagged at 7140'. Tubing plugged. Laid down 73 joints. TOOH to remove plug in tubing. TIH and spot 25 sacks Class "C" from 5525-5400'. Laid down 39 joints. Spot 25 sacks Class "C" from 4250-4100'. Laid down 78 joints. Spot 25 sacks Class "C" from 1725-1600'. Laid down 53 joints. Perforated 4 holes at 450'. Spotted 115 sacks Class "C" to circulate cement to surface between 5-1/2" casing and 8-5/8" casing. Left 5-1/2" casing full of cement. Witnessed by Jack Griffen with OCD in Hobbs. Installed regulation dry hole marker. PLUGGED AND ABANDONED. Plugging completed June 17, 1993.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE

Production Clerk

DATE August 1, 1993

TYPE OR PRINT NAME

Rusty Klein

TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY

Jack Griffen

TITLE

DATE

FEB 09 1995

CONDITIONS OF APPROVAL, IF ANY: