

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
POST OFFICE BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER
2. Name of Operator Read & Stevens, Inc.		
3. Address of Operator P.O. Box 1518, Roswell, NM 88201		
4. Location of Well UNIT LETTER D 554 FEET FROM THE North LINE AND 554 FEET FROM THE West LINE. SECTION 24 TOWNSHIP 13S RANGE 32E NMPM		
5. Elevation (Show whether DF, RT, GR, etc.) 4307' GL		

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-3487
7. Unit Agreement Name -
8. Farm or Lease Name North Baum
9. Well No. 4
10. Field and Pool, or Wildcat Und. Baum Upper Penn
12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER Perforate & Acidize	<input checked="" type="checkbox"/>		

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-1-86 Clean out 9775'-9802', 27', w/bulldozer bailer, TOH w/tbg. Prep to perf Tues 4-1-86 am.
- 4-2-86 TI w/perf guns, could not get blw 9775', TI w/bailer, bail junk. SION.
- 4-3-86 TO w/bailer, TI w/perf gun, perf 9789', 9785', 9729', pull guns, TI w/tbg & isolation pkr, acdz bott perf @ 9789', w/500gals 15% NE acd, went on vac, move up to 2nd perf @ 9785', press up to brk dwn, tbg leak. SION.
- 4-4-86 Perf @ 9785', acdz, avg press 1800psi, max press 3500psi, avg rate 3 BPM, ISIP 1200psi, acdz w/500gals 15% NE acd. Perf @ 9729', acdz, avg press 3600psi, max 4000psi, avg rate .8 BPM, max rate 1 BPM, acdz w/500gals 15% NE acd, GIH w/sd line to pull stdg vlv, wldht pull loose. SION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. Stevens TITLE Drilling and Production Manager DATE April 4, 1986

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE APR 8 - 1986

CONDITIONS OF APPROVAL, IF ANY: