STATE OF NEW MEXICO

EN	ERGY AND MINERALS DE	PAR	TME	NT	
	(
	DISTRIBUTION				
	BANTA FE				
	FILE				
	U.3.0.3.				
	LAND OFFICE	<u> </u>		İ	

CONDITIONS OF APPROVAL, IF ANYI

OIL CONSERVATION DIVISION

		0.2			J.1	Form C-103	
DISTRIBUTION			P. O. BO	X 2088		Revised 10	
SANTA FE		SA	ANTA FE, NEW	MEXICO 87501			
FILE						Sa. Indicate Type of Lesse	
U.3.0.3.		Į.				State X Fee	
LAND OFFICE		1				5. State Otl & Gas Lease No.	
OPERATOR		j					
						L-521	~~~
	SUNDR	Y NOTICES AN	ND REPORTS ON	WELLS			////
(DO NOT USE THIS !	ORM FOR PRO	POSALS TO PHILL OF	TO DEEPEN OF PLUG	DACK TO A DIFFERENT RES	ERVOIM.		////
						7. Unit Agreement Name	
OIL GAI							
	<u> L</u>	07 H C #+				8. Farm or Lease Harre	
Name of Operator						1	
Yates Pet	roleum (Corporation				Coastal "ACT" State	:
Address of Operator						9. Weil No.	
	/.+% C+	Artocia	NM 88210			1	
	4111 31	., Artesia,	M1 00210			10. Field and Pool, c: wildcat	
Location of Well					•	1	
UNIT LETTERP		660	South	660	FEET FROM	Tulk Penn	
UNIT LETTER			1000 181				777
Post		23	14	.s 32	E		1111
THE LAST	LINE, SECTI	on	TOWNSHIP	S RANGE	NMPM.		////
						inninnitititi	44
	WILL	15. Ele	vation (Show whether	DF, RT, GR, etc.)		12, County	////
	//////	(11111)	4288.1'	GR		Lea	////
<i></i>	~~~~	777777					
•	Check	Appropriate Be	ox To Indicate 1	Nature of Notice,	Report or Ot	her Data	
NOT	ICE OF II	NTENTION TO:	:	1	SUBSEQUEN'	T REPORT OF:	
ſ	\neg						
RFORM REMEDIAL WORK		P	LUG AND ABANDON	REMEDIAL WORK	⊢	ALTERING CASING	<u> </u>
MPORARILY ABANDON				COMMENCE DRILLING	OFHS.	PLUG AND ABARDONMEN	,T 🖳
LL OR ALTER CASING	\neg	c	HANGE PLANS	CASING TEST AND CEN	ENT JOS		
	-			OTHER Intern	ediate Cas	ing	X
			[VI			<u> —</u> см
OTHER							
		(61 - 1		inite and mine partices	· dotas inalidina	estimated date of starting any pro	20054
work) SEE HULE 1103		perations (Clearly	state att pertinent de	tatts, and give pertinent	dutes, including	, estimated date of statelity any pro	,posca
			00 11 7 55	40601	Cuido obo	o sot at 4268! Flo	a t
6-21-85.	Ran 102	jts 8-5/8"	32# J-55 cas:	ing set 4200.	Guide Sho	e set at 4268'. Floa	ac
collar set	42261.	Cemented w	/1600 sx Pace	esetter Lite +	5#/sx salt	+ 1/4%/sx Celloseal	•
Toiled in	7/200 es	Class "C"	Neat. Compre	essive strength	of cement	- 950 psi in 12 hrs	•
Talled III	// 200 SZ	Dumand r	1.00 to 1500	nci released r	ressure an	d float held okay.	
PD 6:45 PM	0-21-03). pumped t	orug to 1500 j	111-1 7.00	AW 6 22 85	WOC 12 hre and 15	
Cement cir	culated	50 sx to pi	it. WOC. Dr	illed out /:00	AM 0-22-03	6. WOC 12 hrs and 15	
min. NU a	nd teste	ed to 1000 p	osi for 30 mi	nutes, OK. Red	luced hole	to 7-7/8". Drilled	
plug and r							
prug and r		** *******					
		•					
			•				
				÷			
. I hereby certify that th	information	s above is true and	complete to the best	of my knowledge and b	elief.		
1 /	4						
V/ -			~ T	maduation Cura	rvieor	7-9-85	
Muanila	للجاري	Tillell_	TITLE <u></u>	roduction Supe	T A TOOT	_ DATE	
-	7 7 7 7	1311 13 20 20					
		187 。2013年 5日 日本	र िष्			4	
. 3	arthur r	The British will					