

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	WELL API NO. 30-025-29310
2. Name of Operator MWJ Producing Company	5. Indicate Type of Lease STATE ☒ FEE ☐
3. Address of Operator 400 W. Illinois, Ste 1120, Midland, TX 79701	6. State Oil & Gas Lease No. LG 2612
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line	7. Lease Name or Unit Agreement Name Saunders 10 State
Section <u>10</u> Township <u>14S</u> Range <u>33E</u> NMPM <u>100</u> County <u></u>	8. Well No. 3
10. Elevation (Show whether DF, RKB, RT, CR, etc.) 4221.7 G.L.	9. Pool name or Wildcat Upper Penn

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER: ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Completed Operations: 9/85
3 3/8 set @ 410' OH-17 1/2 TOC Surface
8 5/8 set @ 4142 OH-11 TOC Surface
5 1/2 set @ 10150 OH- 7 7/8 TOC 5450
TOP Salt - 1654
Open Perfs - 9802 - 9880

4/94

CIBP + 2 sks 9894
Perfs - 9916-74

Estimated Date of Starting: 6/15/96
Proposed Operations:

Set CIBP @ 9750
4 sks cmt 9750

Cut 5 1/2 5200' - 208 @ 2000
50 sks 5150 - 5250 Tag
50 sks 4100 - 4200
30 sks 360 - 460
10 sks Surface - 10'

Dry Hole Marker
Circ 10 ppg mud between plugs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Engineer

DATE

TYPE OR PRINT NAME Mark Dehlinger

TELEPHONE NO.

(This space for Stamp Use)

APPROVED BY

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

JUL 23 1996
DATE

CONDITIONS OF APPROVAL IF ANY: