

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-2612

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator MWJ PRODUCING COMPANY	8. Farm or Lease Name Saunders 10 State
3. Address of Operator 400 W. Illinois Suite 1100 Midland, Texas 79701	9. Well No. 4
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat Saunders Permo Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4211.4' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Perf &amp; acidize "C"</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/27/87: MI & RU PU. Unseated pump. Pulled rods & pump. Released tbg anchor & pulled 2-3/8" tbg.  
3/28-29: SD for weekend.  
3/30/87: RU CRC, ran & set CIBP @ 9957'. Ran SSN, 302 jts 2-3/8" tbg & 10' sub, flanged up w/SN @ 9934'. RU Dowell, loaded & tstd well to 3000 psi. Released pressure. Circ w/210 bbls 2% KCWL wtr. Sptd 1000 gals 15% HCL ac. RD Dowell & POOH. CRC perf "C" zone from 9872-9904' & 9930-9934' 2 SPF w/4" OD csg gun.  
3/31/87: Ran Baker Model R-3 pkr, SSN & 298 jts 2-3/8" tbg. Set pkr @ 9788.52' w/13000# & flanged up. Swbd, rec 120 bw w/trace of oil.  
4/1/87: Rel pkr & added 4 jts 2-3/8" tbg. Reset pkr @ 9919' w/10000# tension & flanged up. Swbd. Ran Baker Model 4-3 pkr w/BP, perf sub, SSN, 10' sub, 301 jts 2-3/8" tbg, 6' sub & 4' sub. Set pkr @ 9914' w/15000# tension & flanged up. Swbd.  
4/2/87: Swbd.  
4/3/87: Swbd. POOH & LD pkr. Ran MA jt w/BP, perf sub, SSN, Baker Anchor Catcher w/20000# shear & 300 jts 2-3/8" EUE tbg. Set Anchor Catcher w/10000# & flanged up w/SN @ 9858.42'. Ran repaired pump & rods & hung well on. RD & MO.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pat Drexler TITLE Pat Drexler - Agent DATE 4/6/87

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 8 1987

CONDITIONS OF APPROVAL, IF ANY:

RECORDED  
APR 7 1977  
JOBS OFFICE