

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Newhall Resources	8. Farm or Lease Name Speight
3. Address of Operator P.O. Box 8629 Midland, TX 79708	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>13-S</u> RANGE <u>38-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Bronco Siluro/Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3806.5	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up Halliburton and ran 265 joints of 7" 29#/ft. P-110 flush joint casing to 10,391'. Cemented casing with 325 sack class "H" 50/50 poz-mix w/4% Gel, 3# salt, 0.4% CFR-2 & 0.5% Halad 22-A. Tailed in w/100 sack Class "H" 3#/Salt & 0.4% CFR-2 and 0.6% Halad 22-A. Plug down on casing @ 6:30 A.M. 9-10-86. WOC for 36 hours and drilled out shoe. Went in hole to 10,666 (top of fish) and set a 125 sx. Class "H" kick-off plug back to 10,440'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. E. Brusenhan</u>	TITLE <u>Production Manager</u>	DATE <u>9-15-86</u>
ORIGINAL SIGNED BY JERRY SEXTON		
APPROVED BY <u>DISTRICT 1 SUPERVISOR</u>	TITLE _____	DATE <u>SEP 18 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

SEP 17 1986

G. C. D.  
HOBBS OFFICE