

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Newhall Resources		8. Farm or Lease Name Speight
3. Address of Operator P.O. Box 8629 Midland, TX 79708		9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>13-S</u> RANGE <u>38-E</u> NMPM.		10. Field and Pool, or Wildcat Bronco Siluro/Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3819		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up Haliburton and spotted a 100 sack Class H cement plug @ 9700'. Waited on cement for 4 hours. Went back in hole and tagged cement @ 9814'. Spotted a 45 sack Class H plug @ 7900', 45 sacks Class H at 5990', 45 sack Class H at 4658' and a 45 sack Class "C" cement plug @ 2200'. Set a 10 sack plug at surface and installed dry hole marker. Release rig @ 10 p.m. on 5-20-86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. S. Brunerhan</u>	TITLE <u>Production Manager</u>	DATE <u>5-23-86</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>ATIGE</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
MAY 23 1986
OFFICE
HONORARY OFFICE