STATE UP NEW ME	XILU
ENERGY AND MINERALS DE	PARTMEN
DISTRIBUTION	1 1 1

## P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-103 - Revised 10-1-78

SANTA FE, NEW MEXICO 87501	KEA1260 10-1-18
V.S.O.S.	5a. Indicate Type of Lease
LAND OFFICE	State Fee X
OPERATOR	5, State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1.  OIL XX WELL OTHER-	7, Unit Agreement Name
2. Name of Operator	8, Farm or Lease Name
Newhall Resources	
J. Address of Operator	Speight
P.O. Box 8629 Midland, Texas 79708	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER A . 660 PEET PROM THE NORTH LINE AND 660 PEET PRO	BRONCO SILVER / DEVENION
UNIT LETTER , PEET PROM THE LINE AND FEET PROM	
THE East LINE, SECTION 15 TOWNSHIP 13-S RANGE 38-E NAMED	
TOWNSHIPRANGERANGE	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3819 D.F.	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
	T REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER Conducted DST	<u>#1</u> (X)
OTHER	·
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	
$\cdot$	
Drilled to 9669' in Dolomite, Lime & Shale. Ran DST #1	from 9520 - 9669.
Had a total recovery of 632' of oil/gas cut drilling mud.	
@ 3:30 p.m. 4/21/86.	9
•	
$\cdot$	
	•
	•
	•
•	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Skrusenhan J.E. Brusenhan Title: Production Manager	DATE 4-23-86
ORIGENAL SIGNED BY JERRY SEXTEN	ABE 6 2 1000
APPROVED BY THE DISTRICT I SUPERVISOR TITLE	BATE APR & 9 1001