

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
30-025-29791	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Apache Corporation		8. Farm or Lease Name State QE "13"
3. Address of Operator 7666 E. 61st Street, Suite #500, Tulsa, OK 74133		9. Well No. 2
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>12S</u> RANGE <u>34E</u> N.M.P.M.		10. Field and Pool, or Wildcat Ranger Lake Penn
11. Elevation (Show whether DF, RT, GR, etc.) 4132.6' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CASING SET AT: 13-3/8" 54.5# K-55 ST&C @ 430' - Cemented to surface.  
8-5/8" 32# K-55 & S-80 ST&C @ 4,197' - Cemented to surface.  
7-7/8" hole was drilled to TD of 10,555'.

Norton Drilling Co., Rig No. 4 drilled the well. Production casing was not run on this well. The rig was waiting on approval to plug-and-abandon (verbal approval was obtained). Therefore, we want to start operations to P&A by 1:30 am 01/07/87.

Propose to P&A as follows:

1. TIH with drillpipe open-ended. Spot a 100' cement plug (50 sxs of Class H) from 10,212' - 10,312' (Top of Penn).
2. Pull DP up to 9253' and spot a 100' (50 sxs) cement plug from 9153' - 9253' (Top of Wolfcamp).
3. Pull DP up and spot a 100' plug (50 sxs) from 7698'-7798' (Top of Abo).
4. Pull DP up and spot a 100' plug (50 sxs) from 5541'-5641' (Top of Glorietta).
5. Pull DP up and spot a 100' plug (50 sxs) from 4147'-4247' (8-5/8" casing shoe).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Tim McElmurry</u>	TITLE <u>Regional Drilling Supervisor</u>	DATE <u>01/06/87</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>JAN 15 1987</u>

CONDITIONS OF APPROVAL, IF ANY:

THIS DOCUMENT IS NOT TO BE REPRODUCED  
WITHOUT THE WRITTEN PERMISSION OF  
THE NEW MEXICO DEPARTMENT OF ENERGY AND MINERALS

RECEIVED  
JAN 14 1981  
OCD  
HOBBS OFFICE