

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Yates State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Gladiola Wolfcamp	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator	
TXO Production Corp.	
3. Address of Operator	
900 Wilco Bldg., Midland, Texas 79701	
4. Location of Well	
UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>850</u> FEET FROM	
THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>12-S</u> RANGE <u>38-E</u> NMPL.	
15. Elevation (Show whether DF, RT, GR, etc.)	
3821 GL & 3833 KB	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-22-87 RU Peterson Rig. SPUD 15" hole @ 9:00 pm, 9-21-87.  
 9-23-87 Ran 12 jts 11 3/4" 42# H-40 ST&C f/457.30'. Set @ 457' w/450 sx Class "C" cmt, 2% CaCl. PD @ 12:30 pm, 9-22-87. Circ 75 sx cmt. WOC 18 hrs. Test to 1000#, ok.  
 9-24-87 Drilling 11" hole.  
 thru  
 9-26-87  
 9-27-87 TD'd 11" hole.  
 9-28-87 RU & ran 42 jts 8 5/8" 28# S-80 ST&C f/1665.77'. Ran 18 jts 8 5/8" 24# S-80 ST&C f/778.62'. Ran 52 jts 8 5/8" 24# K-55 ST&C f/2036.87'. Set @ 4476'. Cmt w/1250 sx BJ Lite, 6% gel & 10% salt, 250 sx Class "C" w/2% CaCl. PD @ 1:30 am, 9-28-87. WOC.  
 9-29-87 WOC total of 18 hrs. Ran temp svy. TOC @ 680'. Test to 1000#, ok. Now drilling 7 7/8" hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Beth Cune TITLE Secretary DATE 9-29-87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

DATE OCT 1 1987