Submit 3 Copies to Appropriate District Office

State of New Mexico Energy inerals and Natural Resources Department

Form C-103 Revised 1-1-89

P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO.
DISTRICT II Santa Fe. New Mexico 87504-2088	30-025-30149
P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
	LG-4903
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL OTHER	Lazy Tree AMF State Com
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
·	North Baum Morrow Gas Pool
4. Well Location	
Unit Letter A: 660 Feet From The North Line and 660	Feet From The <u>East</u> Line
Section 12 Township 13S Range 32E	NMPM Lea County
Section 12 Township 135 Range 32E	VIIIIIIIIIII
//////////////////////////////////////	
11. Check Appropriate Box to Indicate Nature of Notice, Re	eport, or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON XX REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CE	EMENT JOB
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.	ding estimated date of starting any proposed
Propose to plug and abandon well as follows:	
1. GIH w/tubing & load hole.	
2. Spot a 25 sack minimum cement plug from 11525-11428' to	o cover Morrow perforations
11478-11483'. Tag plug.  3. Spot a 25 sack minimum cement plug from 11300-11078' to	o cover Atoka perforations
11138-11240'. Tag plug.	o cover mone possession
4. Spot a 25 sack minimum cement plug from 10740-10634' to	o cover Strawn perforations
10684-10690'. Tag plug.  5. Spot a 25 sack minimum cement plug from 10000-9800' to	cover squeezed Wolfcamp
perforations 9858-9948'.  6. Spot a 25 sack minimum cement plug from 9240-9100' to	cover Wolfcamp perforations
9181-9190'. Tag plug.	cover worldamp periorations
CONTINUED ON NEXT PAGE:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	0.07.05
SIGNATURE THE Production C	Clerk DATE 2-27-95
TYPE OR PRINT NAME Rusty Klein	TELEPHONE NO. 505/748-147
	BUTTO OF AMOUNT
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON	MAR 6.1 1005
DISTRICT   SUPERVISOR	DATE

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies to Appropriate District Office

State of New Mexico Energ: inerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

OIL CONSERVATION DIVISION

WELL API NO.

P.O. Box 1980, 110001, 1411 80240	P.O. Box 2088		30-025-30149	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. LG-4903	
	A LOS DEPOSTO ON LIVE	1.0		
( DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOI	S AND REPORTS ON WEL SALS TO DRILL OR TO DEEPEN R. USE "APPLICATION FOR PEF FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL OAS WELL WELL WELL	OTHER		Lazy Tree AMF State Com	
2. Name of Operator	ON		8. Well No.	
YATES PETROLEUM CORPORATI	ON		9. Pool name or Wildcat	
<ol> <li>Address of Operator</li> <li>South 4th St., Artesi</li> </ol>	a. NM 88210		North Baum Morrow Gas Pool	
4. Well Location			FIOTEN BUGIN MOTTON CUB TOOT	
Unit Letter A: 660	Feet From The North	Line and660	Feet From The <u>East</u> Line	
Section 12	Township 13S Ra	nge 32E	NMPM Lea County	
	7///	7' GR	<i>\(\)</i>	
Check Apr	propriate Box to Indicate N		eport, or Other Data	
NOTICE OF INTEN	-		SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB		
OTHER:		OTHER:		
12. Describe Proposed or Completed Operations work) SEE RULE 1103.  CONTINUED FROM PREVIOUS	PAGE:			
7: Stretch casing to find free point. Cut and pull 5-1/2" from as deep as possible.				
Top of cement is at $8100$ '. 8. Spot a 35 sack cement plug thru tubing from 50' below $5-1/2$ " stub. Tag plug.				
Must be at least 50' above stub.				
9. Spot a 35 sack cement plug from 7556' to cover Abo top at 7506'.  10. Spot a 35 sack cement plug from 5416' to cover Glorieta top at 5366'.				
$_{\text{min}}$ Plug must be at least 50' up inside 8-5/8" casing.				
12. Spot a 35 sack ceme	nt plug from 522' to	o cover depth o	r 13-3/8" shoe at 472'.	
13. Set a 15 sack cemen	t plug at surface.			
14. Install regulation	abandonment marker.			
	CONTINUED ON	NEXT PAGE:		
I hereby certify that the information above is true and	complete to the best of my knowledge and	belief.		
SIGNATURE & USTUP	lu m	Production (	Clerk 2-27-95	
TYPEOR PRINT NAME Rusty Klein			<u>тецерноме но. 505/748-1</u> 471	

(This space for State Use)

- DATE -- TITLE -APPROVED BY-

## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy inerals and Natural Resources Department

Form C-103 Revised 1-1-89

CONDITIONS OF AFFROVAL, IF ANY:

OIL CONSERVATION DIVISION

P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		WELL API NO. 30-025-30149
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mex	ico 87504-2088	5. Indicate Type of Lease  STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. LG-4903
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE (FORM C	ICES AND REPORTS ON VOPOSALS TO DRILL OR TO DEE RVOIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A RPERMIT	7. Lease Name or Unit Agreement Name
I. Type of Well: OIL GAS WELL WELL	OTHER		Lazy Tree AMF State Com
2. Name of Operator	A MT ON		8. Well No.
YATES PETROLEUM CORPOR	RATION		9. Pool name or Wildcat
3. Address of Operator 105 South 4th St., Art	tesia, NM 88210		North Baum Morrow Gas Pool
4. Well Location			
Unit Letter A: 66	O Feet From The North	Line and 66	60 Feet From The <u>East</u> Line
Section 12	Township 13S	Range 32E weiher DF, RKB, RT, GR, etc.)	NMPM Lea County
	'//////λ	305.7' GR	
11. Check	Appropriate Box to Indic	ate Nature of Notice,	Report, or Other Data
NOTICE OF IN			BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	,	X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIF	NG OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	•	CASING TEST AND	CEMENT JOB
OTHER:			
<ol> <li>Describe Proposed or Completed Oper work) SEE RULE 1103.</li> </ol>	rations (Clearly state all pertinent desc	ails, and give pertinent dates, inc	luding estimated date of starting any proposed
CONTINUED FROM PREVIO	US PAGE:	•	
NOTE: Heavy mud will	be placed between a	all plugs.	
CIBP's may be set at cost is comparable.	11428', 11078', 1063 Each CIBP will be ca	34' and 9100' in papped with 35' of	place of cement plugs if cement.
NOTIFY NMOCD - HOBBS	(505-393-6161) 24 HG	OURS PRIOR TO COM	MENCING PLUGGING OPERATIONS.
I hereby certify that the information above is t	me and complete to the best of my knowled	dge md belief. Production	Clerk
SIGNATURE DUSLEY	Min	mie	
TYPEOR PRINT NAME RUSty Kle	in		TELEPHONE NO. 505/748-147
(This space for State Use)			
		тпъ	DATE
APPROVED BY		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	